Use TAMS-HydInfra Suggested Repair Method to develop an automated Culvert Repair Cost Estimate



bonnie.peterson@state.mn.us HydInfra Coordinator 18SEP2018

Statewide Pipe Repairs Cost Estimate from TAMS-HydInfra Suggested Repair Report could be automated

			F	Repair method							
A A	B C		1.1	- 2.2	Н	1	L	R			
1	Repair m	e			ntract av	verage bid		Contract			
2 3 District	1	District	1		Unit Pi	Cost	tract	Total Cost			
4	CIPL	1 0				\$183.					
6	Jack			Grout		\$77.	387 165				
8	Reset		. 3	lack	165 374	374					
9 10	Trench		F	Paved Invert	\$26,3	\$40	212 010	\$5,405,504			
11 District	2 CIPL		F	Reset	-	\$323	374 533				
13	Grout Jack		9	Slipline		\$1,552	383 593				
15	Paved Inv	(-	<u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u></u>	0 4 0 .597				
16	Reset			rench	\$2,4	<u> </u>	U I U ,980				
17	Slipline	45	3	562 \$93.22 foot			\$365,255				
18	Trench	21	- 3	633 \$65.37 foot	\$26,36	2.84 each	\$726,406	\$1,893,341			
19 District	3						0010				
20	Grout	—— In 2010	In 2010, HydInfra data with Suggested Repair - 518,691								
22	Jack	Matha	Method was used to calculate costs for repair \$1.025.585								
23	Paved In	ert IVIELIIO									
24	Reset	or repla	acen	nent of MnDOT's	\$29,643						
25	Slipline	wide	wide by DS Johnston and Solsrud								
26	Trench	wide, b	y Do		JSIUU	\$915,860					

TAMS-HydInfra Inspection finds bad culverts and suggests a repair method for each

- HydInfra Culvert Inventory and Inspection captures pipe traits:
 - Size
 - Shape
 - Material
 - Defects
 - Depth of cover
- Suggested Repair Method is an automated selection process that sorts bad pipes by traits to estimate types of repairs needed
- Costs could be applied to all HydInfra pipes based on the Suggested Repair. This was done in a spreadsheet in 2010, using ballpark costs.

TAMS-HydInfra Suggested Repair sorts pipes by traits



"Suggested Repair Method" selects bad culverts for 7 potential repairs

	Α	В	C	D	E	F	G	Н	J	K	L	М	S	Х	Z	
		Route		Roadway	Current Pipe	Current Inside	Inside Width	Inside Height	Pipe Width	Pipe Height	Total Length	Cover at Upstream Road		Inspection	Overall Conditio	V
1	Pipe 💌	Numb	ВМР 💌	Type 🔽	Shap	Material 🗾 💌	(In) 💌	(In) 💌	(In) 💌	(In) 💌	(Ft) 💌	Edge (Ft) 🔽	Inv Suggested Repai	Date 💌	n 💌	
1358	2181552	MN23	174.0545	Centerline	Round	Corg. Steel (CSP)	24	24	24	24	75	8	Install Pipe - Trench	7/19/2017	4 - Severe	
1361	384619	MN23	174.566	Centerline	Box	Concrete	48	72	36	60	75	8	Reset	7/19/2017	3 - Poor	
1366	2304896	MN23	176.3186	Centerline	Box	Concrete	48	72	48	72	100	8	Reset	7/19/2017	2 - Fair	
1367	2181741	MN23	176.3344	Mainline	Round	Concrete	30	30	24	24	80	15	Reset	7/19/2017	4 - Severe	
1369	2181742	MN23	176.5738	Mainline	Round	Concrete	24	24	24	24	75	4	Joint Repair	5/9/2017	3 - Poor	
1370	2181743	MN23	177.0911	Mainline	Round	Concrete	24	24			60	4	Reset	8/1/2017	4 - Severe	
1371	2181744	MN23	178.1267	Mainline	Round	Concrete	24	24			80	4	Joint Repair	5/9/2017	3 - Poor	
1375	2181745	MN23	178.9889	Mainline	Round	Concrete	24	24	24	24	100	15	Joint Repair	8/1/2017	3 - Poor	
1382	2181734	MN23	180.6827	Mainline	Round	Concrete	24	24	24	24	200	15	Reset	8/1/2017	4 - Severe	
1386	2181735	MN23	180.9052	Mainline	Round	Concrete	30	30	36	36	60	4	Reset	8/1/2017	3 - Poor	
1505	2246391	MN23	196.2964	Centerline	Round	Corg. Steel (CSP)	24	24	24	24	400	15	Paved Invert	7/16/2018	4 - Severe	
1536	2246346	MN23	199.2569	Median	Round	Concrete	18	18	18	18	10	4	Reset	7/16/2018	4 - Severe	
1550	2304968	MN23	206.0624	Mainline	Round	Corg. Steel (CSP)	18	18	18	18	70	2	Reset	11/2/2017	3 - Poor	
1562	2181608	MN23	208.0934	Mainline	Round	Concrete	30	30	30	30	172	4	Reset	11/2/2017	3 - Poor	
1566	2181611	MN23	208.6363	Mainline	Round	Corg. Steel (CSP)	18	18	18	18	66	4	Paved Invert	11/2/2017	3 - Poor	
1706	2246071	MN23	218.7151	Mainline	Round	Concrete	24	24	24	24	88	4	Reset	8/24/2016	3 - Poor	
1726	2246072	MN23	219.7427	Mainline	Round	Concrete	30	30	30	30	60	4	Reset	9/5/2017	4 - Severe	
1747	2246078	MN23	222.589	Mainline	Round	Concrete	24	24	24	24	66	4	Reset	9/6/2017	3 - Poor	
1823	2246667	MN23	230.4245	Centerline	Round	Concrete	24	24	24	24	138	20	Joint Repair	7/16/2018	4 - Severe	
1831	2246668	MN23	231.0052	Mainline	Round	Concrete	24	24	24	24	80	8	Joint Repair	7/16/2018	4 - Severe	
1834	2246669	MN23	231.3603	Centerline	Round	Concrete	30	30	30	30	100	8	Joint Repair	9/4/2018	4 - Severe	

Suggested Repair Method is calculated in a TAMS data field.

The sorting process for HydInfra Suggested Repair is described in this flowchart



17) CIPP Liners cured with hot water may contain Styrene that has caused fish kills in streams. Capture all heated water used in resin-curing process and truck to a proper disposal site.

Pipes under deep cover are more difficult and expensive to open trench

tp://oridge/Hydraulics

9 = NA (not applicable)

fraforMBMT html

Flowchart – HydInfra Suggested Repair Method for Highway Culverts (PDF)

Concrete pipe Suggested Repair sorting process covers the most common Concrete pipe problems

TAMS-HydInfra Pipe Flowchart Repair Concrete Pipes





Suggested Repair for Corrugated Steel or Aluminum Culverts differs from Concrete



MnDOT Maintenance captured <u>Culvert Repair Costs</u> that can be applied to Suggested Repairs. See 2014-2015 Summary

Average Estimated Maintenance Cost of Culvert Repair							
Repair Category	Culvert Categories	Number of Repairs	Average Repair Cost				
Trench New Pipe	All	314	\$ 8,430				
	Highway ¹		\$32,170				
	Side ²		\$ 9,610				
	Entrance ³		\$ 5,160				
Slipline		47	\$12,570				
Reset Apron and Pipe		66	\$ 3,000				
Replace Apron and Pipe		52	\$ 3,000				
Joint Repair		33	\$ 2,710				
Pipe Extension		15	\$ 4,060				
Hole Repair		4	\$ 2,000				
Fill Void		6	\$ 1,020				
Other		13	\$11,270				
All Culvert Repairs		550					

¹ Highway culverts include: centerline, mainline, median, CD and ramp-loop

² Side culverts include: city, county, township, frontage, cross-over

³ Entrances culverts include: entrance, farm entrance and field entrance

Culvert Repair Category is described in <u>Repair Made</u> <u>Examples with photos</u>

Separated Aprons are common in Concrete culverts. Suggested Repair is Reset, about \$3000 each*



- Trench_New_Pipe
- Slipline
- Review_for_Repair
- Reset
- Paved_Invert
- NA No_Repair_Indicated
- Joint_Repair
- Jack
- Cured_in_Place_Pipe

Construction District

"Reset" suggested repairs are shown as yellow dots.

*Cost per reset is from <u>2014 - 2015</u> <u>Drainage Maintenance Data</u> <u>Summary (PDF)</u> Big short-coming:

We don't have simple costs available for culvert repairs or installations done by construction contract.

TAMS still needs construction costs to automate repair cost estimates.