

STS CONSULTANTS, LTD.



**Mn/DOT Bridge #9616
Asbestos & Regulated
Waste Inspection Report,
Minneapolis, Minnesota**

Mn/DOT Environmental Offices
St. Paul, Minnesota

STS Project 30070-XA



ASBESTOS AND REGULATED WASTE INSPECTION REPORT

Bridge #9616

East 42nd Street over I-35W in Minneapolis, Minnesota

Prepared For:

Minnesota Department of Transportation (Mn/DOT)
395 John Ireland Boulevard, M.S. 620
St. Paul, MN 55155-1899

Prepared By:

STS Consultants, Ltd.



10900 - 73rd Avenue North, Suite 150
Maple Grove, Minnesota 55369
Telephone: 763-315-6300
Fax: 763-315-1836

January 2006

CONTENTS:

Section 1 - Site Specifics and Certification

Section 2 - Summary of Actions Required For This Demolition

Section 3 - Summary of Asbestos and Regulated Wastes

Section 4 - Qualifications

Appendix I - Site Location, Sampling Location Diagram and Site Photographs

Appendix II - Chain of Custody Forms and Analytical Results

Appendix III - Licenses

SECTION 1

Site Specifics and Certification

Project Overview:

STS has completed the Asbestos and Regulated Waste Assessment of Bridge #9616 for Mn/DOT. The location of the bridge is shown on Figure 1. The specific location of this bridge in relation to other bridges along the Crosstown I-35W/TH 62 corridor is shown on Figure 2. The work was completed in general accordance with the Scope of Work and Deliverables identified in Exhibit A of State Contract No. 88629.

To document the asbestos and regulated waste assessment work, STS obtained photographs of the bridge including:

- Bridge plate number, if available,
- A general distance photograph,
- The underside and top of the bridge,
- Areas of specific interest,
- Asbestos containing material (ACM) sample locations, and
- Regulated waste locations, if identified.

Copies of the photographs are included in Appendix I. The sample locations are shown on Figure 3. The site specifics and results are presented in the remaining portion of this report.

Bridge: BR #9616

Bridge Dimensions: Length = 199', Width = 64.3', # Lanes = 2, # Spans = 4

Year Built: 1964

State Project Number: SP: 2782-281, Trunk Highway Number (TH): I-35W & 62; Asbestos and Regulated Waste Assessment – 20 Bridges

Parcel: N/A

Location: East 42nd Street over I-35W in Minneapolis, Minnesota
(see copies of site map Appendix I).

Number and type of Structure/s: One (1) bridge

Current Owner: Mn/DOT

Expected Disposition of the Structure: Demolition

Licensure: MDH certified asbestos inspectors conducted the inspection (Appendix III).

Mn/DOT Bridge #9616
Asbestos and Regulated Waste
Inspection Report
STS Project 30070-XA

Certification: The undersigned certifies that this asbestos inspection was performed in compliance with MN Rules 4620.3460.

Signature: William B. Tepley
William B. Tepley
Certified Asbestos Inspector
License #A19763

Date: 1/20/06

Certification: The undersigned certifies that this asbestos and regulated waste inspection and report was performed under my direct supervision and I have reviewed its contents and find it to meet or exceed Mn/DOT's contract requirements.

Signature: Suzanne Murawski
Suzanne Murawski
Certified Hazardous Materials Manager
License #08967

Date: 1/20/06

SECTION 2

Bridge #9616 Summary of Actions Required For This Demolition

Asbestos Summary: Asbestos Containing Materials (ACMs) were identified on Bridge #9616 at the following locations:

- Joint sealant on bridge sidewalk contained 5% asbestos = 2,150 linear feet (see Photograph #10).
- Caulk in electric junction boxes on bridge contained 5% asbestos = 20 inches³ (located in 16 electrical boxes on the north side of the bridge) (see Photograph #12).
- Transite utility piping under bridge contained 15% asbestos = 12 transite pipes (4-1/2" O.D.) approximately 200 linear feet per pipe (see Photograph #16).

The ACMs, identified in the Asbestos Summary (above), are required to be removed and properly disposed of in accordance with MnDOT Specifications, prior to demolition (see documents in Section 3 for the detailed sample locations, amounts, conditions and summary inventory of suspect materials).

Regulated Waste Summary: (see Section 3 for the inventory of regulated wastes)

Lead: Lead gaskets (48% lead concentration) were identified under the bridge guard railings during the inspection (see Photograph #19). Approximately 52 lead containing gaskets (size 8" x 8" x 1/4") were identified between the concrete guard railing and the steel railings on the bridge.

Mercury: No mercury containing devices were noted during the inspection.

PCBs: No PCBs containing equipment was noted during the inspection.

CFC's: No CFC containing equipment was noted during the inspection.

Treated Wood: Green treated wood guard rail support posts were identified beneath the bridge deck during the inspection (see Photograph #21). In addition, creosote treated timber piles were identified beneath the piers and abutments during review of the detail drawings (see Figure 3).

Household Hazardous Waste: No household hazardous waste was noted during the inspection.

White Goods: No white goods were noted during the inspection.

Solid Waste: No solid waste was noted during the inspection.

Regulated Waste is required to be removed for demolition (see documents in Section 3 for the detailed sample locations, amounts, conditions and summary inventory of regulated wastes).

The lead gaskets are required to be removed/disposed prior to demolition. The portion of creosote treated timber piles and green treated crash barrier posts required to be removed for bridge demolition shall be managed and disposed in accordance with Mn/DOT specifications.

SECTION 3

Summary of Asbestos and Regulated Wastes at Bridge #9616

If the structure becomes scheduled for demolition rather than a move, the following asbestos and regulated materials/wastes must be removed prior to demolition.

Parcel Number NA
 Building Name Bridge #9616
 Address of Structure East 42nd Street over I-35W in Minneapolis, Minnesota
 Inspection Date October 10 and November 14, 2005

Category I and II

Location	Sample Description	% Asbestos	Quantity	Item	Condition	Sample #'s/ Photo #
Sidewalk Joint Compound	Sealant	ND	NA	NA	NA	A-1 / #5
Sidewalk/Bridge Walk Joint Compound	Sealant	ND	NA	NA	NA	A-2 / #6
Gasket Expansion Joint	Gasket	ND	NA	NA	NA	A-3 / #7
Bridge Deck/Railing Joint Compound	Sealant	ND	NA	NA	NA	A-4 / #8
Mid-Span Bridge Deck Joint Sealant	Sealant	ND	NA	NA	NA	A-5 / #9
Bridge Sidewalk Sealant Mid-Span (approx. 1/2" width)	Sealant	5%	2,150 lin./ft.	Chrysotile	Good	A-6 White Layer / #10
Bridge Sidewalk Sealant Mid-Span	Sealant	ND	NA	NA	NA	A-6 Black Rubber / #10
Bridge Sidewalk Sealant Mid-Span	Sealant	ND	NA	NA	NA	A-6 Black Hard Layer / #10
Brown Material Below Electric Box	Grout	ND	NA	NA	NA	A-7 / #11
Electric Caulk on Junction Box	Caulk	5%	20 inches ³ (16 boxes)	Chrysotile	Good	A-8 White Layer / #12
Electric Caulk on Junction Box	Caulk	ND	NA	NA	NA	A-8 Black Layer / #12
SW Wing Wall Joint Compound	Membrane	ND	NA	NA	NA	A-9 / #13
Joint Compound BTW Footing & Base of Deck	Membrane	ND	NA	NA	NA	A-10 / #14
Joint Compound BTW Footing & Slope Concrete	Membrane	ND	NA	NA	NA	A-11 / #15
Transite Piping (4-1/2" O.D.)	Piping	15%	2400 ft.	Chrysotile	Good	A-12 / #16
Joint at Base of Pier	Membrane	ND	NA	NA	NA	A-13 / #17
Electric Box Gasket	Gasket	ND	NA	NA	NA	A-14 / #18

ND = None Detected

NA = Not Applicable

P-# = Photograph (Photo) Number (see Appendix I)

Lab Analysis/Chain of Custody records are enclosed for all samples.

Mn/DOT Bridge #9616
 Asbestos and Regulated Waste
 Inspection Report
 STS Project 30070-XA

Friable

Location	Sample Description	% Asbestos	Quantity (ft. ²)	Item	Condition	Sample #'s
Total Square Feet	NA	NA	NA	NA	NA	NA

Definitions

Sample Description *Type of Homogeneous material i.e. sheetrock, siding*
Condition Excellent
 Good
 Poor
Quantity *only if contains >1% asbestos otherwise NA*

ND = None Detected

NA = Not Applicable

Lab Analysis/Chain of Custody records are enclosed for all samples.

Mn/DOT Building Regulated Waste Inspection Form
One Form Per Bridge

Company Performing the Inspection STS Consultants, Ltd.
 Company's State Work Order Number Contract #: 88629
 Company Address 10900 - 73rd Avenue North, Suite 150, Maple Grove, MN 55369
 Company Telephone 763-315-6300
 Inspectors Name William B. Tepley/Suzanne Murawski

Mn/DOT District
 State Project Number SP Number: 2782-281
 Parcel Number NA
 Building Name Bridge #9616
 Address of Structure East 42nd Street over I-35W in Minneapolis, MN
 Inspection Date October 10 and November 14, 2005

Inspected Items	Item	Quantity (if none found, state "none")	Location
CFC's	NA	None	NA
<i>Heat pumps</i>	NA	None	NA
<i>Air Conditioners (central)</i>	NA	None	NA
<i>Air Conditioners (window)</i>	NA	None	NA
Fire Extinguishers	NA	None	NA
Freezers	NA	None	NA
Other (name)	NA	None	NA
PCB	NA	None	NA
<i>Ballasts</i>	NA	None	NA
<i>Transformers</i>	NA	None	NA
<i>HID Capacitors</i>	NA	None	NA
Mercury	NA	None	NA
<i>Fluorescent Bulbs</i>	NA	None	NA
HID Lamps	NA	None	NA
Mercury Vapor	NA	None	NA
<i>Thermostats</i>	NA	None	NA
<i>Switches</i>	NA	None	NA
Lead	See below	See below	See below
<i>Lead Plumbing</i>	NA	None	NA
<i>Flaking lead based paint*</i>	NA	None	NA
<i>Bridge railing gasket</i>	Gasket (Pb-1 = 48% lead)	52 gaskets 500 inches ³ (8"x8"x1/4")/ea.	Bridge railing gasket (see Photograph #19)
Treated Wood	See below	See below	See below
<i>Creosote</i>	Treated timber piles	Unknown	Located under piers and abutments (see Figure 3)
<i>Green treated wood</i>	Guard rail support posts	Unknown	Located under bridge deck (see Photograph #21)
Other (name if possible)	NA	None	NA

* Lead based paint is paint which contains lead in a concentration of at least 0.5%.

Mn/DOT Bridge #9616
 Asbestos and Regulated Waste
 Inspection Report
 STS Project 30070-XA

Inspected Items	Item	Quantity (if none found, state "none")	Location
Hazardous/Regulated Wastes	NA	None	NA
<i>Paint (oil/latex)</i>	NA	None	NA
<i>Oil</i>	NA	None	NA
<i>Antifreeze</i>	NA	None	NA
<i>Fuels (name if possible)</i>	NA	None	NA
<i>Lead Acid batteries</i>	NA	None	NA
<i>Pesticides</i>	NA	None	NA
<i>Fertilizers</i>	NA	None	NA
<i>Unlabeled Wastes</i>	NA	None	NA
<i>Televisions</i>	NA	None	NA
<i>Radios</i>	NA	None	NA
<i>Computers</i>	NA	None	NA
<i>Refractory Brick/Mold (cadmium)</i>	NA	None	NA
<i>Other</i>	NA	None	NA
Solid Wastes	NA	None	NA
<i>Furniture</i>	NA	None	NA
<i>White Goods (refrigerators, stoves, dishwashers etc)</i>	NA	None	NA
<i>General Trash (estimate yards)</i>	NA	None	NA
<i>Other</i>	NA	None	NA
Other	NA	None	NA
<i>Septic System</i>	NA	None	NA
<i>Flammable Waste Trap</i>	NA	None	NA
<i>Sediment Trap</i>	NA	None	NA
<i>Other</i>	NA	None	NA
<i>White Goods</i>	NA	None	NA

SECTION 4

Qualifications


Accessible areas of the bridge were observed for suspected ACMs and regulated wastes. Inaccessible areas such as spaces within the concrete structure or buried utilities associated with the bridge, were not observed. Additionally, any electrical wires and/or utility conduits associated with the bridge were not sampled for safety reasons. If unobserved ACMs and/or regulated wastes are discovered during demolition activities, the ACMs and regulated wastes should be documented, handled and disposed of according to appropriate Minnesota State Rules regulating these activities.

The analysis and recommendations in this report are based on the data included herein. The report was prepared in accordance with generally accepted practices exercised by members of the profession currently practicing in this area under similar conditions. No other warranty, expressed or implied, is made. The scope of the report is limited to the specific project and location described herein and a description of the project represents an understanding of significant aspects in reference to the site.

Appendix I

Bridge #9616

Figure 1 - Bridge Location Diagram
Figure 2 - I-35W/TH 62 Crosstown Bridge Corridor Diagram
Figure 3 - Sampling Location Diagram
Site Photographs




STI Engineering Copyright © 1999, All Rights Reserved. STI 10/99. Revised 1/04.



STS CONSULTANTS
 10900 - 73rd Avenue North
 Maple Grove, MN 55369
 763-315-6300
 www.stsconsultants.com
 Copyright ©2004, By: STS Consultants, Ltd.


Bridge Location Diagram
Mn/DOT Bridge #9616
East 42nd Street Over I-35W
Minneapolis, Minnesota

Drawn:	AJC
Checked:	WBT
Approved:	RLD
PROJECT NUMBER	30070-XA
FIGURE NUMBER	1



N
 NOT DRAWN TO SCALE

NOTE: BRIDGE LOCATION DIAGRAM BASED ON SITE PLAN PROVIDED BY MNDOT.




STS CONSULTANTS
 10900 73rd Ave. N., Suite 150
 Maple Grove, MN 55369
 763-315-6300
 www.stsconsultants.com
 Copyright ©2006, by STS Consultants, Ltd.

**MNDOT I-35W / T.H. 62 CROSSTOWN BRIDGE CORRIDOR DIAGRAM
 ASBESTOS & REGULATED WASTE ASSESSMENT
 MINNEAPOLIS - RICHFIELD, MINNESOTA**

Drawn:	TAK	1/17/2006
Checked:	AC	1/17/2006
Approved:	WBT	1/17/2006
PROJECT NUMBER	630070XA	
FIGURE NUMBER	2	



STS CONSULTANTS
10900 73rd Ave. N., Suite 150
Maple Grove, MN 55369
763-315-6300
www.stsconsultants.com
Copyright ©2006, By: STS Consultants, Ltd.




GENERAL PLAN VIEW
N.T.S.


LEGEND

- A# ASBESTOS SAMPLE LOCATION
- Pb# LEAD SAMPLE LOCATION
- ⊙ SAMPLE NOT VISIBLE IN CURRENT VIEW
- ⊠ AUGER HOLE LOCATION

N.T.S. NOT TO SCALE



TRAVERSE SECTION THRU BRIDGE DECK
N.T.S.



GENERAL ELEVATION
N.T.S.

SAMPLING LOCATION DIAGRAM
MnDOT BRIDGE NUMBER 9616
E. 42nd STREET OVER I-35W
MINNEAPOLIS, MINNESOTA

Drawn :	TAK	1/17/2006
Checked:	AJC	1/17/2006
Approved:	WBT	1/17/2006
PROJECT NUMBER	630070XA	
FIGURE NUMBER	3	

X:\PROJECTS\630070XA\IG630070XA-01.dwg, 9616, 1/18/2006 7:46:15 PM, STS_PLOTSTAMP.STS_PLOTSTAMP



PHOTOGRAPHIC LOG


Client Name: Mn/DOT		Site Location: Bridge #9616	Project No.: 30070-XA
Photo No.: 1	Date: 10/10/05		
Direction Photo Taken: N/A			
Description: Bridge identification plate for Bridge #9616. This bridge is located at East 42nd Street over I-35W in Minneapolis, Minnesota.			

Photo No.: 2	Date: 10/10/05	
Direction Photo Taken: Looking northwest		
Description: View of the bottom profile of Bridge #9616. Green treated wood guard rail posts were identified under the bridge.		



PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No. 30070-XA
-------------------------------	---------------------------------------	--------------------------------

Photo No. 3	Date: 10/10/05
-----------------------	--------------------------

Direction Photo Taken:
Looking west across I-35W

Description:
View of the underside of Bridge #9616.

Note transite piping along the steel girders spanning the length of the bridge.



Photo No. 4	Date: 10/10/05
-----------------------	--------------------------

Direction Photo Taken:
Looking west-northwest along 42nd Street

Description:
View of the top of Bridge #9616.





PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No. 30070-XA
-------------------------------	---------------------------------------	--------------------------------

Photo No. 5	Date: 10/10/05
Direction Photo Taken: Looking down at sidewalk joint on the SW side of bridge	
Description: Asbestos sample A-1 Sidewalk joint compound.	




Photo No. 6	Date: 10/10/05
Direction Photo Taken: Looking down at sidewalk/bridge walk on the SW corner of bridge	
Description: Asbestos sample A-2 Sidewalk/bridge walk joint compound	





PHOTOGRAPHIC LOG



Client Name: Mn/DOT		Site Location: Bridge #9616	Project No. 30070-XA
Photo No. 7	Date: 10/10/05		
Direction Photo Taken: Looking down at gasket expansion joint on the south side of bridge			
Description: Asbestos sample A-3 Gasket for the expansion joint plate			

Photo No. 8	Date: 10/10/05		
Direction Photo Taken: Looking down at bridge deck/railing joint on the south side of bridge			
Description: Asbestos sample A-4 Bridge deck/railing joint compound			



PHOTOGRAPHIC LOG



Client Name: Mn/DOT		Site Location: Bridge #9616	Project No. 30070-XA
Photo No. 9	Date: 10/10/05		
Direction Photo Taken: Looking down at mid-span bridge deck			
Description: Asbestos sample A-5 Mid-span bridge deck joint sealant.			

Photo No. 10	Date: 10/10/05		
Direction Photo Taken: Looking down at bridge sidewalk on the south side of the central portion of the bridge			
Description: Asbestos sample A-6 Bridge sidewalk sealant mid-span Three separate sealant layers were identified: 1) White layer 2) Black hard layer and 3) Rubber layer			



PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No.: 30070-XA
-------------------------------	---------------------------------------	---------------------------------

Photo No.: 11	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Looking down below electric box on north side of bridge above northbound I-35W

Description:
Asbestos sample A-7
Brown material below electric box



Photo No.: 12	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Facing electric box on NW side of bridge

Description:
Asbestos sample A-8
White layer and black layer - electric caulk on junction box





PHOTOGRAPHIC LOG

Client Name: Mn/DOT		Site Location: Bridge #9616	Project No.: 30070-XA
Photo No.: 13	Date: 10/10/05		
Direction Photo Taken: Facing wing wall on SW corner of bridge			
Description: Asbestos sample A-9 SW wing wall joint compound			

Photo No.: 14	Date: 10/10/05		
Direction Photo Taken: Facing footing of west bridge abutment			
Description: Asbestos sample A-10 Joint compound btw footing & base of deck support			



PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No.: 30070-XA
-------------------------------	---------------------------------------	---------------------------------

Photo No.: 15	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Facing footing of west bridge abutment

Description:
Asbestos sample A-11
Joint compound btw footing & slope concrete



Photo No.: 16	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Looking up at the transite piping from the south

Description:
Asbestos sample A-12
Transite piping under bridge
12 transite pipes x 4-1/2" O.D. were identified spanning the length of the bridge.





PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No.: 30070-XA
-------------------------------	---------------------------------------	---------------------------------

Photo No.: 17	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Looking down at base of pier on west end of bridge


Description:
Asbestos sample A-13
Joint at base of pier



Photo No.: 18	Date: 10/10/05
-------------------------	--------------------------

Direction Photo Taken:
Facing electric box on NW side of bridge

Description:
Asbestos sample A-14
Electric box gasket





PHOTOGRAPHIC LOG


Client Name: Mn/DOT		Site Location: Bridge #9616	Project No. 30070-XA
Photo No. 19	Date: 10/10/05		
Direction Photo Taken: Facing railing gasket on north side of bridge			
Description: Lead sample Pb-1 Railing gasket			

Photo No. 20	Date: 10/11/05	
Direction Photo Taken: Looking down hole at NE corner of bridge adjacent to wing wall		
Description: A hole was advanced by STS adjacent to the northeast wing wall on Bridge #9616. No membrane was observed adjacent to the wing wall.		



PHOTOGRAPHIC LOG

Client Name: Mn/DOT	Site Location: Bridge #9616	Project No. 30070-XA
-------------------------------	---------------------------------------	--------------------------------

Photo No. 21	Date: 1/12/06
------------------------	-------------------------

Direction Photo Taken:
Looking south along I-35W

Description:
Green treated wood guard rail support posts were observed under the bridge.



Mn/DOT Bridge #9616
Asbestos and Regulated Waste
Inspection Report
STS Project 30070-XA

Appendix II

Bridge #9616

Chain of Custody Forms and Analytical Results



ANALYTICAL

CHAIN OF CUSTODY

ASBESTOS

350504738

EMSL Representative:		EMSL Reference Number:	MN03
Your Company Name:	STS Consultants	EMSL-Bill to:	Same
Street:	10900 73 rd Ave South	Street:	
Box #:	Suite 150	Box #:	
City/State:	Maple Grove, MN Zip: 55369	City/State:	
Verbal Results to:	email to tepley@stscons.com	Fax Results to:	Bill Tepley
Telephone #:	763-315-6300	Fax #:	763-315-1836
Project Name/Number:	CROSSTOWN - 30070 XA	Purchase Order #	

MATRIX BRIDGE 9616 TURNAROUND TIME

- | | | | | | | | |
|--|---|-------------------------------|--------------------------------------|-------------------------------|----------------------------------|--|-----------------------------------|
| <input type="checkbox"/> Air | <input type="checkbox"/> Floor Tile | <input type="checkbox"/> Soil | <input type="checkbox"/> Wipe | <input type="checkbox"/> RUSH | <input type="checkbox"/> 6 Hours | <input type="checkbox"/> 24 Hours | <input type="checkbox"/> 48 Hours |
| <input checked="" type="checkbox"/> Bulk | <input type="checkbox"/> Drinking Water | <input type="checkbox"/> Dust | <input type="checkbox"/> Waste water | Contact Lab | <input type="checkbox"/> 3 Days | <input checked="" type="checkbox"/> 5 Days | 10 days |

- | | | |
|--|--|------------------------------------|
| PCM | PLM | <input type="checkbox"/> Comments: |
| <input type="checkbox"/> NIOSH 7400 | <input type="checkbox"/> EPA 600/R-93/116 | |
| <input type="checkbox"/> MN Dept of Health | <input type="checkbox"/> NOB | |
| <input type="checkbox"/> Other: | <input type="checkbox"/> Point Count (400 point) | |
| | <input type="checkbox"/> Test Until Positive | |
| | <input type="checkbox"/> Other: | |

- | | | | |
|--|---|--|---------------------------------------|
| TEM AIR | TEM BULK | TEM WATER | TEM WIPE |
| <input type="checkbox"/> AHERA | <input type="checkbox"/> Chatfield | <input type="checkbox"/> EPA 100.1 (all fibers) | <input type="checkbox"/> Quantitative |
| <input type="checkbox"/> EPA Level II | <input type="checkbox"/> NOB | <input type="checkbox"/> EPA 100.2 (Long fibers >10um) | <input type="checkbox"/> Qualitative |
| <input type="checkbox"/> NIOSH 7402 | <input type="checkbox"/> Micro Vac-Quantitative | <input type="checkbox"/> NY 198.2 | |
| <input type="checkbox"/> MN Dept of Health | <input type="checkbox"/> Micro Vac-Quantitative | | |
| | <input type="checkbox"/> Drop Mount-Qualitative | | |

- TEM DUST**
- ASTM D-5755-95
- Qualitative

BRIDGE 9616

Client Sample # (s)	A-1 . A-13	Total Samples:	13
Relinquished:	Bill Tepley, STS	Date:	10/13/05
Received:	Mike Scott	Date:	10/13/05
Received:		Date:	
		Time:	7:45 AM
		Time:	7:50 AM

SAMPLE DATE	SAMPLE NUMBER	LOCATION	VOLUME (If Applicable)
10-10-05	A-1	SIDEWALK JOINT COMPOUND	
	A-2	SIDEWALK / BRIDGE WALK JOINT COMPOUND	
	A-3	GASKET EXPANSION JOINT	
	A-4	BRIDGE DECK RAILING JOINT COMPOUND	
	A-5	MIDSPAN BRIDGE DECK JOINT SEALANT	
	A-6	BRIDGE SIDEWALK SEALANT MIDSPAN	
	A-7	BROWN MATERIAL BELOW ELECTRIC BOX	
	A-8	ELECTRIC CAULK ON JUNCTION BOX	
	A-9	SW WING WALL JOINT COMPOUND	
	A-10	JOINT COMP BTW FOOTING & BASE OF BRIDGE DECK	
	A-11	JOINT COMP BTW FTG & SLOPE CONCRETE	
	A-12	TRANSITE PIPING, 4 1/2" OD	
	A-13	JOINT AT BASE OF PIER	

EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: minneapolislab@emsl.com

Attn: **Bill Tepley**
STS Consultants LTD
10900 73rd Avenue North
Suite 150
Maple Grove, MN 55369

Customer ID: STSC50
Customer PO:
Received: 10/13/05 7:50 AM
EMSL Order: 350504738

Fax: (763) 315-1836 Phone: (763) 315-6335

Project: **CROSS TOWN-30070 XA 9616 BRIDGE #9616**

EMSL Proj:
Analysis Date: 10/18/2005
Report Date: 10/20/2005

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-1 350504738-0001	SIDEWALK JOINT COMPOUND	Gray/Black Non-Fibrous Heterogeneous		100% Non-fibrous (other)	None Detected
A-2 350504738-0002	SIDEWALK/BRID GE WALK JOINT COMPOUND	Black/Brown Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-3 350504738-0003	GASKET EXPANSION JOINT	Brown Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (other)	None Detected
A-4 350504738-0004	BRIDGE DECK RAILING JOINT COMPOUND	Black/Brown Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (other)	None Detected
A-5 350504738-0005	MIDSPAN BRIDGE DECK JOINT SEALANT	Black Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-6 WHITE LAYER 350504738-0006	BRIDGE SIDWALK SEALANT MID SPAN	White Fibrous layers: 3		95% Non-fibrous (other)	5% Chrysotile
A-6 BLACK RUBBER 350504738-0014	BRIDGE SIDWALK SEALANT MID SPAN	Black/Brown Non-Fibrous layers: 3		100% Non-fibrous (other)	None Detected

Analyst(s)

Paul Senne (16)



or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client.

Analysis performed by EMSL Minneapolis (NVLAP #200019-0)

EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: minneapolislab@emsl.com

Attn: **Bill Tepley**
STS Consultants LTD
10900 73rd Avenue North
Suite 150
Maple Grove, MN 55369

Customer ID: STSC50
Customer PO:
Received: 10/13/05 7:50 AM
EMSL Order: 350504738

Fax: (763) 315-1836 Phone: (763) 315-6335
Project: **CROSS TOWN-30070 XA 9616 BRIDGE #9616**

EMSL Proj:
Analysis Date: 10/18/2005
Report Date: 10/20/2005

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-6 BLACK HARD LAYER 350504738-0015	BRIDGE SIDWALK SEALANT MID SPAN	Black/Gray Non-Fibrous layers: 3		100% Non-fibrous (other)	None Detected
A-7 350504738-0007	BROWN MATERIAL BELOW ELECTRIC BOX	Tan Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected
A-8 WHITE LAYER 350504738-0008	ELECTRIC CAULK ON JUNCTION BOX	White Non-Fibrous layers: 2		95% Non-fibrous (other)	5% Chrysotile
A-8 BLACK LAYER 350504738-0016	ELECTRIC CAULK ON JUNCTION BOX	Black Non-Fibrous layers: 2		100% Non-fibrous (other)	None Detected
A-9 350504738-0009	SW WING WALL JOINT COMPOUND	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected
A-10 350504738-0010	JOINT COMP BTW FOOTING & BASE OF BRIDGE DECK	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (other)	None Detected

Analyst(s)

Paul Senne (16)



or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client.

Analysis performed by EMSL Minneapolis (NVLAP #200019-0)

EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: minneapolislab@emsl.com

Attn: **Bill Tepley**
STS Consultants LTD
10900 73rd Avenue North
Suite 150
Maple Grove, MN 55369

Customer ID: STSC50
Customer PO:
Received: 10/13/05 7:50 AM
EMSL Order: 350504738

Fax: (763) 315-1836 Phone: (763) 315-6335

Project: **CROSS TOWN-30070 XA 9616 BRIDGE #9616**

EMSL Proj:
Analysis Date: 10/18/2005
Report Date: 10/20/2005

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-11 350504738-0011	JOINT COMP BTW FTG & SLOPE CONCRETE	Brown/Black Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (other)	None Detected
A-12 350504738-0012	TRANSITE PIPING, 4 1/2" OD	Cream Fibrous Homogeneous		85% Non-fibrous (other)	15% Chrysotile
A-13 350504738-0013	JOINT AT BASE OF PIER	Brown/Black Fibrous Homogeneous	30% Cellulose	70% Non-fibrous (other)	None Detected

Analyst(s)

Paul Senne (16)



or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client.

Analysis performed by EMSL Minneapolis (NVLAP #200019-0)

EMSL Analytical, Inc.

14375 23rd Avenue North, Minneapolis, Mn 55447

Phone: (763) 449-4922 Fax: (763) 449-4924 Email: minneapolislab@emsl.com

Attn: **Bill Tepley**
STS Consultants LTD
10900 73rd Avenue North
Suite 150
Maple Grove, MN 55369

Customer ID: STSC50
Customer PO:
Received: 11/30/05 4:10 PM
EMSL Order: 350505396

Fax: (763) 315-1836 Phone: (763) 315-6335
Project: **Crosstown 30070-XA**

EMSL Proj:
Analysis Date: 12/6/05
Report Date: 12/7/05

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-14	Electric Box	Gray/Tan	5% Synthetic	15% Non-fibrous (other)	None Detected
350505396-0001	Gasket	Fibrous	80% Cellulose		
		Heterogeneous			

Analyst(s) _____

Rachel Travis (1)



or other approved signatory

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. Samples reported as <1% or none detected may require additional testing by TEM to confirm asbestos quantities. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client.
Analysis performed by EMSL Minneapolis (NVLAP #200019-0)

EMSL Analytical

2001 East 52nd St., Indianapolis, IN 46205

Phone: (317) 803-2997 Fax: (317) 803-3047 Email: indianapolislaboratory@emsl.com

Attn: **Bill Tepley**
STS Consultants LTD
10900 73rd Avenue North
Suite 150
Maple Grove, MN 55369


Customer ID: STSC50
Customer PO:
Received: 10/14/05 10:10 AM
EMSL Order: 160511920

Fax: (763) 315-1836 Phone: (763) 315-6335
Project: **CrossTown 30070XA Bridge 9616**

EMSL Proj:
Report Date: 10/19/2005

Lead in Paint Chips by Flame AAS (SW 846 3050B and 7420*)

<i>Lab ID:</i>	<i>Analyzed</i>	<i>RDL</i>	<i>Lead Concentration</i>	<i>Notes</i>
0001	10/19/2005	0.01	48.00 % wt	
<i>Client Sample</i> Pb-1				<i>Collected:</i> 10/13/2005



or other approved signatory

Reporting limit is 0.01 % wt. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied

ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #157245

Date Printed: 10/19/2005 2:30:57 PM

PB w/RDL

Appendix III

Bridge #9616

Licenses

MDH inspector/s license/s

CHMM License

Copies of Analytical Laboratory Accreditation/s

Certificate No: 5LM10190510IR

Expiration Date: October 19, 2006

This is to certify that
William Tepley
has attended and successfully completed an
**ASBESTOS INSPECTOR
REFRESHER TRAINING COURSE**

permitted by
the State of Minnesota under Minnesota Rules 4620.3702 to 4620.3722
and meets the requirements of
Section 206 of Title II of the Toxic Substances Control Act (TSCA)
conducted by

Lake States Environmental, Ltd.

in


White Bear Lake, MN on October 19, 2005


Expiration Date: October 19, 2005



MDH ASBESTOS
INSPECTOR

Certified by:
State of Minnesota
Department of Health
Expires: 10/19/2006
William B Tepley
3253 Webster Ave S
St. Louis Park, MN 55416


Training Instructor


Director, Env. Health Div

No. AI9763 Issued: 10/28/2005

**INSTITUTE OF HAZARDOUS MATERIALS
MANAGEMENT**



Certifies that

Suzanne M. Murawski

has demonstrated understanding of science, knowledge of regulations, competence in management, and maturity of judgment essential to effectively manage hazardous materials and is hereby designated a

Certified Hazardous Materials Manager

Master Level

April 1998

200

8967

Date

Number

Expiration Date

Donald M. Gordon
Executive Director

INSTITUTE OF HAZARDOUS MATERIALS MANAGEMENT
11900 PARKLAWN DR. STE 450 • ROCKVILLE, MD 20852
CHMM
NUMBER
08967
EXPIRATION
DATE
12/2005

SUZANNE MURAWSKI


HAVING MET THE QUALIFICATIONS AND REQUIREMENTS
IS AUTHORIZED TO USE THE TITLE
CERTIFIED HAZARDOUS MATERIALS MANAGER
Valid upon payment of annual fees and compliance with recertification requirements

United States Department of Commerce
National Institute of Standards and Technology

NVLAP[®]

ISO/IEC 17025:1999
ISO 9002:1994

Certificate of Accreditation



EMSL ANALYTICAL, INC.
MINNEAPOLIS, MN

*is recognized by the National Voluntary Laboratory Accreditation Program
for satisfactory compliance with criteria set forth in NIST Handbook 150:2001,
all requirements of ISO/IEC 17025:1999, and relevant requirements of ISO 9002:1994.
Accreditation is awarded for specific services, listed on the Scope of Accreditation, for:*

BULK ASBESTOS FIBER ANALYSIS

March 31, 2006

Effective through

For the National Institute of Standards and Technology
NVLAP Lab Code: 200019-0


National Institute
of Standards and Technology



National Voluntary
Laboratory Accreditation Program

ISO/IEC 17025:1999
ISO 9002:1994

Scope of Accreditation



Page: 1 of 1

BULK ASBESTOS FIBER ANALYSIS

NVLAP LAB CODE 200019-0

EMSL ANALYTICAL, INC.

14375 23rd Avenue North

Minneapolis, MN 55447

Ms. Rachel Travis

Phone: 763-449-4922 Fax: 763-449-4924

E-Mail: minneapolislab@emsl.com

URL: <http://www.emsl.com>

NVLAP Code

Designation

18/A01

EPA-600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

March 31, 2006

Effective through

A handwritten signature in black ink, appearing to read "Gary R. W. [unclear]".

For the National Institute of Standards and Technology



SOUND DATA
LABORATORY QUALITY ASSURANCE PROGRAMS

AIHA
 Your Essential Connection: Advancing Occupational and Environmental Health and Safety Globally
 2700 Prosperity Ave., Suite 250, Fairfax, VA 22031 U.S.A.
 (703) 849-8888; Fax (703) 207-3561; www.aiha.org

AIHA Laboratory Quality Assurance Programs SCOPE OF ACCREDITATION

EMSL Analytical, Inc.
 2001 East 52nd Street, Indianapolis, IN 46205

Laboratory ID: **157245**
 Issue Date: 08/11/2005

The laboratory is approved for those specific field(s) of testing/methods listed in the table below. Clients are urged to verify the laboratory's current accreditation status for the particular field(s) of testing/Methods, since these can change due to proficiency status, suspension and/or revocation. A complete listing of currently accredited Industrial Hygiene laboratories is available on the AIHA website at:
<http://www.aiha.org/LaboratoryServices/html/lists.htm>

The EPA recognizes the AIHA ELLAP program as meeting the requirements of the National Lead Laboratory Accreditation Program (NLLAP) established under Title X of the Residential Lead-Based Paint Hazard Reduction Act of 1992 and includes paint, soil and dust wipe analysis. Air analysis is not included as part of the NLLAP.


Environmental Lead Laboratory Accreditation Program (ELLAP)

Initial Accreditation Date: 09/01/2002

Field of Testing (FoT)	Method	Method Description <i>(for internal methods only)</i>
Airborne Dust	NIOSH 7082	
Paint	EPA SW-846 3050B	
	EPA SW-846 7420	
Settled Dust by Wipe	EPA SW-846 3050B	
	EPA SW-846 7420	
Soil	EPA SW-846 3050B	
	EPA SW-846 7420	

The laboratory participates in the following AIHA testing programs:

- ✓ Paint
- ✓ Soil
- ✓ Airborne Dust
- ✓ Settled Dust by Wipe



The American Industrial Hygiene Association

acknowledges that

EMSL Analytical, Inc.

2001 East 52nd Street, Indianapolis, IN 46205
Laboratory ID: 157245

has fulfilled the requirements of the AIHA Laboratory Quality Assurance Programs (LQAP), thereby, conforming to the ISO/IEC 17025:1999 international standard, *General Requirements for the Competence of Testing and Calibration Laboratories*: The above named laboratory, along with all premises from which key activities are performed, as listed above, have been accredited by AIHA in the following:


ACCREDITATION PROGRAMS

- | | | |
|-------------------------------------|-----------------------------------|-----------------------------------|
| <input type="checkbox"/> | INDUSTRIAL HYGIENE | Accreditation Expires: |
| <input checked="" type="checkbox"/> | ENVIRONMENTAL LEAD | Accreditation Expires: 09/01/2007 |
| <input checked="" type="checkbox"/> | ENVIRONMENTAL MICROBIOLOGY | Accreditation Expires: 12/01/2007 |
| <input type="checkbox"/> | FOOD | Accreditation Expires: |

Specific Field(s) of Testing (FoT)/Method(s) within each Accreditation Program for which the above named laboratory maintains accreditation is outlined on the attached **Scope of Accreditation**. Continued accreditation is contingent upon successful on-going compliance with LQAP requirements. This certificate is not valid without the attached **Scope of Accreditation**.

Larry S. Pierce, PhD, CIH
Chairperson, Analytical Accreditation Board

Roy M. Buchan, DrPH, CIH
President, AIHA



Date Issued: 08/11/2005