

REPORT DOCUMENTATION PAGE	1. Report No. MN/RD - 92/02	2.	3. Recipient's Accession No.
4. Title and Subtitle CULVERT RENEWAL		5. Report Date April, 1992	
7. Author(s) Dave Johnson, Operations Engineer and John Zollars, Research Assistant		6.	
9. Performing Organization Name and Address Physical Research Section Office of Materials and Research Minnesota Department of Transportation 1400 Gervais Avenue Maplewood, MN 55109		8. Performing Organization Rept. No. 9PR5383	
12. Sponsoring Organization Name and Address Minnesota Department of Transportation Office of Materials and Research 1400 Gervais Ave. Maplewood, MN 55109		10. Project/Task/Work Unit No.	
15. Supplementary Notes		11. Contract(C) or Grant(G) No. (C) (G)	
16. Abstract (Limit: 200 words) The Minnesota Department of Transportation is investigating alternative means of culvert renewal in lieu of removal and replacement. Several state of the art renewal techniques were selected for trial on I-35 near Hinckley, Minnesota in an effort to find an inexpensive and less disruptive alternative to removal and replacement of deteriorated culverts. Seven different reliners were placed in concrete and metal pipe, and five joint repair options were placed in concrete pipe. These reliners and repairs were compared using costs, skills and resources required, time, culvert preparation, traffic disruption, work area requirements, placement problems, and grouting procedures. Field performance of the reliners and joint repairs was checked visually after one year to evaluate the short term effects of climate. At this point in time all reliners appeared to be performing adequately. Relining and joint repair should be considered as an inexpensive, time saving, and minimally disruptive alternative to removal and replacement of deteriorated culverts. Smooth reliners are inexpensive, flexible, easy to install and perform better hydraulically than corrugated or ribbed reliners. Savings can be significant in both money and time with very little disruption to the driving public.		13. Type of Report & Period Covered Final Report 1988 - 1992	
17. Document Analysis a.Descriptors Reliners repair sealing sizing cost b. Identifiers/Open-Ended Terms c. COSATI Field/Group		14.	
18. Availability Statement No restrictions. This document is available through the National Technical Information Services, Springfield, VA 22161		19. Security Class (This Report) Unclassified	21. No. of Pages 48
		20. Security Class (This Page) Unclassified	22. Price

CULVERT RENEWAL

Final Report
March 1992

Prepared By

Dave Johnson
Research Operations Engineer

and

John Zollars
Research Assistant

Physical Research Section
Office of Materials and Research
Minnesota Department of Transportation

The contents of this report reflect the views of the authors who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the views or policies of the Minnesota Department of Transportation at the time of publication. This report does not constitute a standard, specification, or regulation.

The authors and the Minnesota Department of Transportation do not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the objective of this report.

TABLE OF CONTENTS

I. BACKGROUND1

II. PURPOSE1

III. APPROACH2

IV. RESULTS7

 A. OVERVIEW7

 B. CULVERT REMOVAL AND REPLACEMENT8

 C. CULVERT RELINERS10

 1. Smooth Polyethylene with Mechanical Joints

 2. Smooth Polyethylene with Fused Joints

 3. Corrugated Polyethylene

 4. Spiral Ribbed Polyvinyl Chloride

 5. Fiberglass

 6. Spiral Ribbed Coated Steel Arch

 7. Cured Resin Impregnated Felt Tube

 D. CULVERT JOINT REPAIR26

 1. Joint Void Sealing and Filling

 2. Joint Sealing

V. RECOMMENDATIONS31

VI. ACKNOWLEDGEMENTS33

VII. APPENDICES:

 A. PRELIMINARY CULVERT INSPECTION

 B. DRAINAGE CHART FROM PLANS

 C. SAMPLE CULVERT RELINING DATA SHEET

 D. ALTERNATIVE COST TABULATION

 E. ALTERNATIVE TIME REQUIREMENT TABULATION

 F. DISTRICT 8 RELINER INSPECTION NOTES

I. BACKGROUND

The replacement of a deteriorated culvert under a roadway is an expensive proposition. The work required to remove and replace (r & r) such a structure is both disruptive to the driving public and to the structural integrity of the existing pavement. Finding an inexpensive and less disruptive alternative would be very desirable.

Minnesota Department of Transportation (Mn/DOT) Maintenance Area 1A based in Duluth was particularly interested in this problem since their area of operations included soil and moisture conditions conducive to the deterioration of corrugated metal culverts. This situation was not identified until 1969 in the Final Report of Minnesota Department of Highways Investigation Number 116, "Serviceability of Corrugated Metal Culverts". Area roadways designed before 1969 included corrugated metal culverts that are now experiencing high deterioration rates.

II. PURPOSE

The objectives of this research project was to investigate alternative means of culvert renewal in lieu of total replacement, to apply several state of the art renewal techniques, and to collect and evaluate the experiences of performing alternative methods of correcting culvert deterioration problems. These alternatives were to be compared using the following criteria:

- Cost
- Skills and resources required
- Time required
- Old culvert preparation
- Traffic disruption
- Work area requirements
- Placement problems
- Grouting procedures

Also we wanted to review the field performance of the alternatives after one year in place to evaluate the short term effects of climate.

It was hoped that this research project would lead the department to accept one or more of the alternatives as a less expensive and less disruptive method than culvert replacement, whether done by contract or Mn/DOT maintenance forces. This project should also serve as a basis for evaluating any future culvert renewal products.

III. APPROACH

The following steps outline the approach taken by Mn/DOT in this research project:


1. Evaluate various culvert repair and relining methods and select some viable renewal alternatives.
2. Inspect and identify deteriorated culverts as possible candidates for repair, relining, or replacement.
3. Match the candidate deteriorated culverts to the selected renewal alternatives.
4. Develop plans and special provisions for a culvert renewal project.
5. Observe and evaluate the execution of the culvert renewal contract.
6. Perform post construction evaluation of renewal methods and materials.
7. Write a research report.

A task force met in 1988 and 1989 to identify, evaluate, and specify various proprietary products that would be used in a demonstration culvert renewal project. This Mn/DOT task force represented:

- Central and District Maintenance
- Central and District Hydraulics
- Central and District Design
- District Construction
- District Materials
- Research Administration and Development
- Physical Research
- Standards
- FHWA

Relining pipe materials that were considered included polyethylene, fiberglass, steel, polyvinyl chloride, and a cured resin impregnated felt tube. Since no long term historical experience with relining was available, the task force felt that the reliners should meet the strength requirements of a new installation, if possible. The task force considered methods of repairing concrete pipe joints and of overlaying the deteriorated bottom of a culvert with a concrete overlay. The intent was that these renewal methods would keep traffic disruption to a minimum. In addition, the task force wanted to include a culvert removal and replacement site on the project to provide a basis for comparisons.

On October 18th, 1988 Mn/DOT staff from the Hydraulics Section, Physical Research Section, and District 1A inspected 59 culverts between Reference Posts 165 and 235 on Interstate 35 between Duluth and the Twin Cities. This stretch of I-35 was constructed between 1962 and 1967, thus predating a recommendation not to use corrugated metal culverts in this area. The purpose of this inspection was to identify deteriorated culverts that might be considered for joint repair, relining, or replacement. A summary of that inspection are in Appendix A. The following photographs show examples of deterioration encountered during the inspection:



Joint separation in a concrete culvert.

