

2016 UNDERWATER BRIDGE INSPECTION REPORT



BRIDGE # 57517 CR 63 over THIEF RIVER

DISTRICT: District 2 COUNTY: Pennington CITY/TOWNSHIP: NORTH
STATE: Minnesota

Date of Inspection: 09/28/2016
Equipment Used:

Owner: County Highway Agency

Inspected By: Schroeder, Brian

Report Written By: Brian Schroeder
Report Reviewed By:
Final Report Date:



TABLE OF CONTENTS

	PAGE NUMBER
UNDERWATER SUMMARY	3
UNDERWATER INSPECTION	4
UNDERWATER INSPECTION PROCEDURES	6
STRUCTURE INVENTORY	7
ELEMENTS	8
PICTURES	11
DRAWINGS	17

UNDERWATER INSPECTION

REPORT SUMMARY

The substructure units inspected at Bridge No. 57517, Piers 1 and 2, were in good condition with no defects of structural significance observed. The channel bottom appeared to be stable with no evidence of significant scour.

INSPECTION FINDINGS

(A) The 20 inch diameter steel pile encasements of both piers from the top of pile down 6 feet were coated. The coating has minor random areas of coating loss on less than one percent of total surface area. In areas of coating loss, the exposed steel exhibited minor corrosion with no appreciable section loss.

(B) The 20 inch diameter steel pile encasement from 6 feet below the top of the pile to the channel bottom has no protective coating (primer only) and corrosion was observed on up to 75 percent of surface area consisting of rust nodules up to ½ inch diameter and minor pitting (less than 1/32 inch deep).

(C) A moderate accumulation of timber debris consisting of 1 foot diameter and smaller branches was observed along both sides and in between piles 1 to 3 at Pier 1.

RECOMMENDATIONS

(A) Monitor the timber debris, and if found to be increasing in the future, removal operations may become warranted.

(B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of sixty (60) months.

Contractor: Ayres Associates & Collins Engineers, Inc.

Contractor Job Number: 9687

UNDERWATER INSPECTION

1. BRIDGE DATA

Bridge #: 57517
Feature Intersected: THIEF RIVER
Facility Carried: CR 63
District: District 2
County: 057 - Pennington

Bridge Description:

The Bridge is a three span structure consisting of a prestressed I-beam superstructure supporting a reinforced concrete deck. The superstructure is supported by two reinforced concrete abutments and two reinforced concrete pier caps founded on 7 piles. The piers are numbered 1 and 2 starting from the south end of the bridge. The abutment and pier footings are supported by steel H-piles.

2. INSPECTION DATA

Professional Engineer/Team Leader: Brian K. Schroeder, P.E.
Inspection Diver: Brian K. Schroeder, P.E.
Date of Underwater Inspection: 09/28/2016
Weather Conditions: Cloudy, 57°F
Underwater Visibility (feet): 1.0
Waterway Velocity (ft/sec): Negligible/None

3. SUBSTRUCTURE INSPECTION DATA

Substructure(s) Inspected: Piers 1 and 2

General Shape:

A 3.5 feet wide by 3.5 feet high reinforced concrete cap supported by seven driven steel H-piles encased by 20 inch diameter steel shell encasements.

Maximum Water Depth at Substructure(s) Inspected (feet): 9.9

4. WATERLINE DATUM

Water Level Reference: The top of the deck at the upstream end of Pier 1
Waterline Elevation (feet): 1110.9
Description: The waterline was approximately 14.5 feet below reference.

5. NBIS CODING INFORMATION

(Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code: 7
Item 61: Channel and Channel Protection: Code: 7
Item 62: Culvert: Code:

Item 92B: Underwater Inspection: Code: Y 48 09/2016

Item 113: Scour Critical Bridge: Code: I

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

Yes No (Mark your selection with an X)

6. STRUCTURAL ELEMENT CONDITION RATING

ELEM #	Element Description	Quantity	Unit	Conditions			
				CS1	CS2	CS3	CS4
202	Steel Column	14	EA	14			
885	Scour	1	EA	1			

UNDERWATER INSPECTION

INSPECTION PROCEDURES

The routine underwater inspection of Bridge 57517 (CR No. 63 over the Thief River) was completed on September, 28, 2016. The underwater inspection was conducted from shore. The inspection was conducted by a team consisting of a PE-Diver with a valid MnDOT Team leader certification, a backup diver and a dive tender. The inspection utilized commercial dive equipment and techniques (SSA and/or SCUBA) in accordance with OSHA regulations. Profiles were taken along the upstream and downstream faces of the bridge and around the periphery of substructure units to determine the presence, location and area of scour.

The bridge elements inspected consisted of two reinforced concrete piers. According to the bridge inventory or design drawings, a 3.5 feet wide by 3.5 feet high reinforced concrete cap is supported by seven driven steel H-piles encased by 20 inch diameter steel shell encasements. Inspection procedures followed FHWA guidance and the MnDOT Bridge and Structure Inspection Program Manual with channel bottom probing to search for foundations. The routine underwater inspection frequency is recommended to remain at 60 months based on those findings and risk factors. Also, inspection procedures should continue to follow the above approach and standard guidance with 100% Level I and 10% Level II intensity efforts.

Minnesota Structure Inventory Report

Bridge ID: 57517

CR 63 over THIEF RIVER

Date: 01/10/2017

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 02 Maint. Area County 057 - Pennington City Township 57011 - NORTH Desc. Loc. 0.2 MI NE OF JCT CSAH 31 Sect., Twp., Range 27 - 154N - 43W Latitude 48 ° 7 ' 54.03 " Longitude 96 ° 10 ' 16.14 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1995 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 3 - COUNTY Date Opened to Traffic On - Off System 1 - ON Legislative District 01A Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 07 - CNTY Number 63 Roadway Name or Description CNTY 63 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point 013+00.230 Detour Length 4.0 mi. Lanes ON 2 UNDER 0 ADT 320 YEAR 2003 HCA DT ADTT % Functional Class 17 - Urban - Collector	Userkey 97 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 99.9 Routine Inspection Date 10/22/2014 Routine Inspection Frequency 24 Inspector Name Schroeder, Brian Status A - Open																				
		+ NBI CONDITION RATINGS +																				
		Deck 8 Unsound Deck % Superstructure 8 Substructure 7 Channel 7 Culvert N																				
	+ RDWY DIMENSIONS +	+ NBI APPRAISAL RATINGS +																				
	If Divided NB-EB SB-WB Roadway Width 44.00 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. 43.9 ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 40.0 ft. Bridge Roadway Width 44.0 ft. Median Width On Bridge ft.	Structure Evaluation 7 Deck Geometry 9 Underclearances N Waterway Adequacy 8 Approach Alignment 8																				
+ STRUCTURE +		+ SAFETY FEATURES +																				
Service On 5 - Highway-pedestrian Service Under 5 - Waterway Main Span Type 5 - Prestress or Precast Main Span Design 01 - Beam Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type Barrel Length Cantilever ID		Bridge Railing 1 - MEETS STANDARDS GR Transition N - NOT REQUIRED Appr. Guardrail 1 - MEETS STANDARDS GR Termini 1 - MEETS STANDARDS																				
	+ MISC. BRIDGE DATA +	+ IN DEPTH INSP. +																				
Number of Spans MAIN: 3 APPR: 0 TOTAL: Main Span Length 65.2 ft. Structure Length 195.6 ft. Deck Width (Out-to-Out) 52.8 ft. Deck Material 1 - Concrete Cast-in-Place Wear Surf Type 1 - Monolithic Concrete Wear Surf Install Year Wear Course/Fill Depth 0.00 ft. Deck Membrane 0 - None Deck Rebars 1 - Epoxy Coated Reinforcing Deck Rebars Install Year 1995 Structure Area (Out-to-Out) 10328 sq. ft. Roadway Area (Curb-to-Curb) 8611 sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 6.00 ft. Curb Height Lt 0.00 ft. Rt 0.83 ft. Rail Type Lt 22 Rt 28	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID Abutment Foundation (Material/Type) 1 - CONC 3 - FTG PILE Pier Foundation (Material/Type) 3 - STEEL 4 - PILE BENT Historic Status 5 - Not eligible	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td></td> <td style="text-align: center;">60</td> <td style="text-align: center;">09/28/2016</td> </tr> <tr> <td>Pinned Asbly.</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical				Underwater		60	09/28/2016	Pinned Asbly.				Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical																						
Underwater		60	09/28/2016																			
Pinned Asbly.																						
Spec. Feat.																						
	+ PAINT +	+ WATERWAY +																				
Year Painted Unsound Paint % Painted Area sq. ft. Primer Type Finish Type		Drainage Area (sq. mi.) 1040.0 Waterway Opening (sf.) 2520 Navigation Control 0 - No nav. control on Pier Protection Nav. Clr. (ft.) Vert. 0.0 Horiz. 0.0 Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code 1 - LOW RISK Year																				
	+ BRIDGE SIGNS +	+ CAPACITY RATINGS +																				
Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 0 - Not Required Vertical N - Not Applicable		Design Load 9 - HS 25 (OR GREATER) Operating Rating 2 - HS TRUCK 42.3 Inventory Rating 2 - HS TRUCK 25.3 Posting VEH: SEMI: DBL: Rating Date 10/17/2013 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				

MINNESOTA BRIDGE INSPECTION REPORT

02/02/2017

BRIDGE 57517 CR 63 OVER THIEF RIVER

County: Pennington Location: 0.2 MI NE OF JCT CSAH 31 Length: 195.6 ft.
 City: Route: 07 - CNTY 63 Ref. Pt.: 013+00.230 Deck Width: 52.8 ft.
 Township: 57011 - NORTH Control Section: Rdwy. Area/ Pct. Unsnd: 8611 sq. ft. / %
 Section: 27 Township: 154N Range: 43W Maint. Area: Paint Area/ Pct. Unsnd: sq. ft. / %
 Span Type: 5 - Prestressed Concrete 2 - Local Agency Bridge Nbr.: Culvert: N/A
 List: Stringer/Multi-beam or Girder Postings:
 NBI Deck: 8 Super: 8 Sub: 7 Chan: 7 Culv: N
 Open, Posted, Closed: A - Open
 MN Scour Code: 1 - LOW RISK

Appraisal Ratings - Approach: 8 Waterway: 8 Unofficial Structurally Deficient N
 Required Bridge Signs - Load Posting: 0 - Not Required Traffic: 0 - Not Required Unofficial Functionally Obsolete N
 Horizontal: 0 - Not Required Vertical: N - Not Applicable Unofficial Sufficiency Rating 99.9

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
38	Reinforced Concrete Slab	Underwater	09/28/2016	10328 SF	10328	0	0	0
		Migrated Values		10328 SF	10328	0	0	0
Notes: SW CORNER SMALL CRACK. (2010) THE REST APPEARS TO BE IN GOOD CONDITION. (2010) NW corner minor crack with efflorescence. (2012) No Chg (2014)								
510 - Wearing Surfaces		Underwater	09/28/2016	8611 SF	8611	0	0	0
		Migrated Values		8611 SF	8611	0	0	0
Notes: Concrete Slab with Bituminous Overlay Notes: MINOR CRACKING, WEST END OF DECK. (2010) No Chg (2014)								
154	Prestressed Concrete Floor Beam	Underwater	09/28/2016	974 LF	974	0	0	0
		Migrated Values		974 LF	974	0	0	0
Notes: APPEAR TO BE IN GOOD CONDITION. (2010) (2014)								
202	Steel Column	Underwater	09/28/2016	14 EA	14	0	0	0
		Migrated Values		14 EA	14	0	0	0
Notes: COLUMNS IN GOOD CONDITION. (2010)(2012)(2014)								
515 - Steel Protective Coating		Underwater	09/28/2016	999 SF	999	0	0	0
		Migrated Values		999 SF	999	0	0	0
Notes: [2016] Migrator assumed quantity of 999 SF and estimated the condition states.								
215	Reinforced Concrete Abutment	Underwater	09/28/2016	152 LF	152	0	0	0
		Migrated Values		152 LF	152	0	0	0
Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:40 CS2:0 CS3:0 CS4:0). BOTH ABUTMENTS IN GOOD CONDITION. (2010) (2014)								
Wingwall notes: NE WINGWALL - IN GOOD CONDITION. (2010) NW WINGWALL - IN GOOD CONDITION. (2010) SW WINGWALL - IN GOOD CONDITION. (2010) SE WINGWALL - IN GOOD CONDITION. (2010)(All No Chg (2014)								
234	Reinforced Concrete Pier Cap	Underwater	09/28/2016	105 LF	105	0	0	0
		Migrated Values		105 LF	105	0	0	0
Notes: BOTH CAPS IN GOOD CONDITION. (2010) (2014)								
311	Movable Bearing	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: BEARINGS APPEAR TO BE IN GOOD CONDITION. (2010) (2014)								

BRIDGE 57517 CR 63 OVER THIEF RIVER

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
313	Fixed Bearing	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: BEARINGS APPEAR TO BE IN GOOD CONDITION. (2010) (2014)								
330	Metal Bridge Railing	Underwater	09/28/2016	197 LF	197	0	0	0
		Migrated Values		197 LF	197	0	0	0
Notes: OVER ALL RAILING APPEARS TO BE IN GOOD CONDITION, BUT MISSING TWO NUTS. (2010) Nuts was replaced. Paint is peeling off, no sign of corrosion. (2014)								
515 - Steel Protective Coating		Underwater	09/28/2016	999 SF	999	0	0	0
		Migrated Values		999 SF	999	0	0	0
Notes: [2016] Migrator assumed CS1 and a quantity of 999 SF.								
331	Reinforced Concrete Bridge Railing	Underwater	09/28/2016	394 LF	394	0	0	0
		Migrated Values		394 LF	394	0	0	0
Notes: APPEARS TO BE IN GOOD CONDITION. (2010) (2014)								
800	Critical Deficiencies or Safety Hazards	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: No critical structural deficiencies or serious safety hazards are present on this structure.								
822	Bituminous Approach Roadway	Underwater	09/28/2016	2 EA	2	0	0	0
		Migrated Values		2 EA	2	0	0	0
Notes: BOTH APPROACHES IN GOOD CONDITION. (2010) East approach minor settling. (2012) Moderate settling (2014) West minor settling (2014)								
883	Concrete Shear Cracking	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to monitor the presence of shear cracking on concrete elements. Pay particular attention to the prestressed concrete beams.								
885	Scour	Underwater	09/28/2016	1 EA	1	0	0	0
891	Other Bridge Signing	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NE END MARKER - UP AND MINOR CONDITION (2010) (2014) NW END MARKER - UP AND IN MINOR CONDITION (2010) (2014) SW END MARKER - UP AND IN GOOD CONDITION (2010) (2014) SE END MARKER - UP AND IN GOOD CONDITION (2010) Minor condition (2014)								
892	Slopes & Slope Protection	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: EAST SLOPE - MINOR SETTLING (2010) (2014) WEST SLOPE - MINOR SETTLING (2010) (2014)								
893	Guardrail	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NE GUARD RAILING IN GOOD SHAPE. (2010) NW GUARD RAILING IN GOOD SHAPE. (2010) SW GUARD RAILING - MISSING FIVE NUTS. (2010) SE GUARD RAILING IN GOOD SHAPE. (2010) All missing nuts was replaced. All guard railing are in good shape. (2014)								

BRIDGE 57517 CR 63 OVER THIEF RIVER

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
894	Deck & Approach Drainage	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: NE WINGWALL - MINOR SETTLING, END IN GOOD SHAPE (2010) NW WINGWALL - MOD. SETTLING, END SEVERE SHAPE (2010) SW WINGWALL - NO SETTLING, END IN GOOD SHAPE (2010) SE WINGWALL - NO SETTLING, END MOD. TO SEVERE (2010) DECK DRAIN PART PLUG (2010) Need to be cleaned in the spring (2014)							
895	Sidewalk, Curb, & Median	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: SIDEWALK - EAST END, THE APPROACH TO WALK HAS ABOUT 1" DROP. (2010) SIDEWALK - WEST END, THE APPROACH TO WALK HAS ABOUT 2 3/4" DROP. (2010) Sidewalk - West End, drop 3" to 4". (2012) No chg (2014)							
899	Miscellaneous Items	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: MINOR DEBRIS AROUND PIERS (2010) SE WINGWALL SMALL TREES. (2010) BOTH SLOPES SMALL BRUSHES (2010) No chg (2014)							
900	Protected Species	Underwater	09/28/2016	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
	Notes: Use this element to track the presence of protected species living on this structure.							

General Notes: 12-5-06 BRUSH HAS BEEN REMOVED AROUND ABUTS, NO STRUCTURAL CHANGES. JJ
SEE ELEMENTS (2010)
See Elements (2012) Update report with underwater bridge inspection report Aug 16,2012
See Elements (2014)

- 58. Deck NBI:
- 36A. Brdg Railings NBI:
- 36B. Transitions NBI:
- 36C. Appr Guardrail NBI:
- 36D. Appr Guardrail Terminal NBI:
- 59. Superstructure NBI:
- 60. Substructure NBI:
- 61. Channel NBI:
- 62. Culvert NBI:
- 71. Waterway Adeq NBI:
- 72. Appr Roadway Alignment NBI:

Inspector's Signature

Reviewer's Signature

Pictures



Photo 1 - Upstream Profile



Photo 2 - Downstream Profile

Pictures



Photo 3 - North Abutment



Photo 4 - South Abutment

Pictures



Photo 5 - Pier 1 North Face



Photo 6 - Pier 1 South Face

Pictures



Photo 7 - Pier 2 North Face



Photo 8 - Pier 2 South Face

Pictures



Photo 9 - Typical Condition at Waterline




Photo 10 - Upstream Channel

Pictures



Photo 11 - Downstream Channel



**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 57517
OVER THE THIEF RIVER
DISTRICT 2, PENNINGTON COUNTY,
CITY OF THIEF RIVER FALLS



INSPECTION AND SOUNDING PLAN

COLLINS ENGINEERS
1599 Selby Avenue
Suite 206
St. Paul, MN 55104
(651) 646-8502
www.collinsengr.com

Drawn By: JCK
Checked By: BKS
Project: 63-9687

AYRES ASSOCIATES
3433 Oakwood Hills Parkway
Eau Claire, WI 54701
www.AyresAssociates.com

Date: SEPT., 2016
Scale: NTS
Figure No.: 1



Note: _____
 Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION	
STRUCTURE NO. 57517 OVER THE THIEF RIVER DISTRICT 2, PENNINGTON COUNTY, CITY OF THIEF RIVER FALLS UPSTREAM AND DOWNSTREAM FASCIA PROFILES	
Drawn By: JCK	Date: SEPT., 2016
Checked By: BKS	Scale: 1"=20'
Project: 63-9687	Figure No.: 2

COLLINS ENGINEERS
 1599 Selby Avenue
 Suite 206
 St. Paul, MN 55104
 (651) 646-8502
 www.collinsengr.com

AYRES ASSOCIATES
 3433 Oakwood Hills Parkway
 Eau Claire, WI 54701
 www.AyresAssociates.com