

2017 UNDERWATER BRIDGE INSPECTION REPORT



BRIDGE # 33506 CSAH 8 over KNIFE RIVER

DISTRICT: District 3

COUNTY: Kanabec

CITY/TOWNSHIP: KNIFE LAKE

STATE: Minnesota

Date of Inspection: 04/06/2017

Equipment Used:

Owner: County Highway Agency

Inspected By: Stuber, Cory

Report Written By: Cory Stuber

Report Reviewed By:

Final Report Date:



TABLE OF CONTENTS

	PAGE NUMBER
UNDERWATER SUMMARY	3
UNDERWATER INSPECTION	4
UNDERWATER INSPECTION PROCEDURES	6
STRUCTURE INVENTORY	7
ELEMENTS	8
PICTURES	12
DRAWINGS	14

UNDERWATER INSPECTION

REPORT SUMMARY

The substructure units inspected at Bridge No. 33506, Piers 1 and 2, were found to be in good to satisfactory condition with no defects of structural significance observed. However, the protective coating/paint system has failed from two feet above the waterline extending to the channel bottom. A severe timber and garbage debris accumulation was observed between the south shoreline and Pier 1. Garbage includes a large corrugated steel pipe with a steel box attached. Pier 2 has one large 16 inch diameter timber log caught on the upstream nose and extending halfway into the main channel. The channel bottom around the substructure units appeared stable, and no scour depressions were observed. This report represents the initial underwater inspection for this structure.

INSPECTION FINDINGS

(A) Overall, the steel of the H-piles of both piers was sound, while the paint system has failed from two feet above the waterline to the channel bottom.

(B) Severe timber debris, up to 1 foot diameter, and garbage have accumulated between Pier 1 and the south shoreline. Garbage includes a large corrugated steel pipe with a steel box attached.

(C) Submerged log, up to 16 inches in diameter, observed from the upstream nose of Pier 2 extending halfway into the main span channel.

(D) Channel bottom material consisted of cobbles, up to 2 feet in diameter.

RECOMMENDATIONS

(A) Monitor the timber debris accumulation at both Piers during future inspections, and if found to be increasing to a more detrimental extent, removal operations may become warranted at that time.

(B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of sixty (60) months.

Contractor: Collins Engineers, Inc.

Contractor Job Number: 9687

UNDERWATER INSPECTION

1. BRIDGE DATA

Bridge #: 33506
Feature Intersected: KNIFE RIVER
Facility Carried: CSAH 8
District: District 3
County: 033 - Kanabec
Bridge Description:

The superstructure consists of three spans. The reinforced concrete deck rests upon steel beams supported on two pile bent piers and two reinforced concrete abutments. The pile bents consist of reinforced concrete pier caps supported by steel H-piles with steel cross-bracing. The substructure units are designated as the South Abutment, Piers 1 and 2, and the North Abutment respectively.

2. INSPECTION DATA

Professional Engineer/Team Leader: Cory Stuber, P.E.
Inspection Diver: Cory Stuber, P.E.
Date of Underwater Inspection: 04/06/2017
Weather Conditions: Sunny, 55°F
Underwater Visibility (feet): 3
Waterway Velocity (ft/sec): 0.5

3. SUBSTRUCTURE INSPECTION DATA

Substructure(s) Inspected: Piers 1 and 2
General Shape:

The bent piers consist of a reinforced concrete pier cap supported by five steel H-piles and steel cross bracing.

Maximum Water Depth at Substructure(s) Inspected (feet): 4.2

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap on the downstream end of Pier 1.
Waterline Elevation (feet): 176.7
Description: The waterline was approximately 11.1 feet below reference.

5. NBIS CODING INFORMATION

(Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code: 6
Item 61: Channel and Channel Protection: Code: 7
Item 62: Culvert: Code:

Item 92B: Underwater Inspection: Code: Y 48 04/2017

Item 113: Scour Critical Bridge: Code: N

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

Yes No (Mark your selection with an X)

6. STRUCTURAL ELEMENT CONDITION RATING

ELEM #	Element Description	Quantity	Unit	Conditions			
				CS1	CS2	CS3	CS4
202	Steel Column	10	EA		10		
885	Scour	1	EA	1			

UNDERWATER INSPECTION

INSPECTION PROCEDURES

The routine underwater inspection of Bridge 33506 (CSAH 8 over the Knife River) was completed on April 6, 2017. The underwater inspection was conducted from shore. The inspection was conducted by a team consisting of a PE-Diver with a valid MnDOT Team Leader certification and a dive tender. Due to waterway conditions at the time of inspection, the inspection could be accomplished by wading in accordance with OSHA regulations. Profiles were taken along the upstream and downstream faces of the bridge and around the periphery of substructure units to determine the presence, location and area of scour.

The bridge elements inspected consisted of two pile bent piers. According to the bridge inventory or design drawings, Piers 1 and 2 were founded on five steel H-piles. Inspection procedures followed FHWA guidance and the MnDOT Bridge and Structure Inspection Program Manual with channel bottom probing to search for foundations. The routine underwater inspection frequency is recommended to remain at a maximum of 60 months based on those findings and risk factors. Also, inspection procedures should continue to follow the above approach and standard guidance with 100% Level I and 10% Level II intensity efforts.

Minnesota Structure Inventory Report

Bridge ID: 33506

CSAH 8 over KNIFE RIVER

Date: 05/12/2017

+ GENERAL +	+ ROADWAY +	+ INSPECTION +																				
Agency Br. No. Crew District 03 Maint. Area County 033 - Kanabec City Township 33010 - KNIFE LAKE Desc. Loc. 0.4 MI S OF JCT CR 88 Sect., Twp., Range 10 - 040N - 24W Latitude 45 ° 58 ' 29.25 " Longitude -93 ° 19 ' 44.41 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1967 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 3 - COUNTY Date Opened to Traffic On - Off System 1 - ON Legislative District 08B Potential ABC 2 - N/A	Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 04 - CSAH Number 8 Roadway Name or Description CSAH 8 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point Detour Length 5.0 mi. Lanes ON 2 UNDER 0 ADT 347 YEAR 2008 HCA DT ADTT % Functional Class 07 - Rural - Major Collector	Userkey 73 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 94.2 Routine Inspection Date 11/18/2015 Routine Inspection Frequency 24 Inspector Name Stuber, Cory Status A - Open																				
		+ NBI CONDITION RATINGS +																				
		Deck 5 Unsound Deck % 5 Superstructure 7 Substructure 6 Channel 7 Culvert N																				
		+ NBI APPRAISAL RATINGS +																				
		Structure Evaluation 6 Deck Geometry 6 Underclearances N Waterway Adequacy 8 Approach Alignment 8																				
		+ SAFETY FEATURES +																				
		Bridge Railing 0 - SUBSTANDARD GR Transition 1 - MEETS STANDARDS Appr. Guardrail 1 - MEETS STANDARDS GR Termini 1 - MEETS STANDARDS																				
		+ IN DEPTH INSP. +																				
		<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 60%;"></th> <th style="width: 10%; text-align: center;">Y/N</th> <th style="width: 15%; text-align: center;">Freq</th> <th style="width: 15%; text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td></td> <td></td> <td style="text-align: right;">04/06/2017</td> </tr> <tr> <td>Pinned Asbly.</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>		Y/N	Freq	Date	Frac. Critical				Underwater			04/06/2017	Pinned Asbly.				Spec. Feat.			
	Y/N	Freq	Date																			
Frac. Critical																						
Underwater			04/06/2017																			
Pinned Asbly.																						
Spec. Feat.																						
		+ WATERWAY +																				
		Drainage Area (sq. mi.) Waterway Opening (sf.) 1164 Navigation Control 0 - No nav. control on Pier Protection <table style="width: 100%; border-collapse: collapse;"> <tr> <td>Nav. Clr. (ft.)</td> <td>Vert. 0.0</td> <td>Horiz. 0.0</td> </tr> </table> Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code N - STBL - LIM Year	Nav. Clr. (ft.)	Vert. 0.0	Horiz. 0.0																	
Nav. Clr. (ft.)	Vert. 0.0	Horiz. 0.0																				
		+ CAPACITY RATINGS +																				
		Design Load 4 - H 20 Operating Rating 2 - HS TRUCK 27.2 Inventory Rating 2 - HS TRUCK 16.2 Posting VEH: SEMI: DBL: Rating Date 04/08/2015 Overweight Permit Codes A N - N/A B N - N/A C N - N/A																				
+ STRUCTURE +	+ RDWY DIMENSIONS +																					
Service On 1 - Highway Service Under 5 - Waterway Main Span Type 4 - Steel Continuous Main Span Design 01 - Beam Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 30 RIGHT Culvert Type Barrel Length Cantilever ID Number of Spans MAIN: 3 APPR: 0 TOTAL: Main Span Length 41.5 ft. Structure Length 111.5 ft. Deck Width (Out-to-Out) 32.7 ft. Deck Material 1 - Concrete Cast-in-Place Wear Surf Type 1 - Monolithic Concrete Wear Surf Install Year Wear Course/Fill Depth 0.00 ft. Deck Membrane 0 - None Deck Rebars 0 - None Deck Rebars Install Year Structure Area (Out-to-Out) 3646 sq. ft. Roadway Area (Curb-to-Curb) 3358 sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. Curb Height Lt 0.75 ft. Rt 0.75 ft. Rail Type Lt 42 Rt 42	If Divided NB-EB SB-WB Roadway Width 30.10 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 28.0 ft. Bridge Roadway Width 30.1 ft. Median Width On Bridge ft.																					
	+ MISC. BRIDGE DATA +																					
	Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID 4 - Bolted Abutment Foundation (Material/Type) 3 - FTG PILE Pier Foundation (Material/Type) 3 - STEEL 4 - PILE BENT Historic Status 5 - Not eligible																					
	+ PAINT +																					
	Year Painted 1967 Unsound Paint % Painted Area sq. ft. Primer Type 1 - Lead - non 3309 Finish Type F - Phenolic Resin Alum																					
	+ BRIDGE SIGNS +																					
	Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 1 - Object Markers Vertical N - Not Applicable																					

MINNESOTA BRIDGE INSPECTION REPORT

05/15/2017

BRIDGE 33506 CSAH 8 OVER KNIFE RIVER

County: Kanabec Location: 0.4 MI S OF JCT CR 88 Length: 111.5 ft.
 City: Route: 04 - CSAH 8 Ref. Pt.: 006+00.400 Deck Width: 32.7 ft.
 Township: 33010 - KNIFE LAKE Control Section: Rdwy. Area/ Pct. Unsnd: 3358 sq. ft. / 5%
 Section: 10 Township: 040N Range: 24W Maint. Area: Paint Area/ Pct. Unsnd: sq. ft. / %
 Span Type: 4 - Steel Continuous 2 - Stringer/Multi- Local Agency Bridge Nbr.: Culvert: N/A
 List: beam or Girder Postings:
 NBI Deck: 5 Super: 7 Sub: 6 Chan: 7 Culv: N
 Open, Posted, Closed: A - Open
 MN Scour Code: N - STBL - LIM SCOUR

Appraisal Ratings - Approach: 8 Waterway: 8 Unofficial Structurally Deficient N
 Required Bridge Signs - Load Posting: 0 - Not Required Traffic: 0 - Not Required Unofficial Functionally Obsolete N
 Horizontal: 1 - Object Markers Vertical: N - Not Applicable Unofficial Sufficiency Rating 94.2

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
12	Reinforced Concrete Deck	Underwater	04/06/2017	3646 SF	3646	0	0	0
		Migrated Values		3646 SF	3646	0	0	0
	Notes: SE end rebar exposed, spalling w/ efforcence.							
510 - Wearing Surfaces		Underwater	04/06/2017	3358 SF	3022	0	336	0
		Migrated Values		3358 SF	3022	0	336	0
	Notes: Top of Concrete Deck with Uncoated Rebar Notes: Numerous areas of cracks & delaminations. Delaminations have been patched w/ Bit. 2015: Most of the patches for delaminations are gone. Due to deck condition, recommend repairs to deck.							
107	Steel Open Girder/Beam	Underwater	04/06/2017	430 LF	377	53	0	0
		Migrated Values		430 LF	377	53	0	0
	Notes: Rusted area on girder NW bridge end. Remainder in good condition. 2015: Some Peeling & beginning to rust.							
515 - Steel Protective Coating		Underwater	04/06/2017	999 SF	876	0	116	7
		Migrated Values		999 SF	876	0	116	7
	Notes: [2016] Migrator assumed quantity of 999 SF and estimated the condition states.							
202	Steel Column	Underwater	04/06/2017	10 EA	0	10	0	0
		Migrated Values		10 EA	0	10	0	0
	Notes: Lower portion of columns rusting. They need to cleaned up & repainted. Easterly 4 columns or N. pier have impact damage.							
515 - Steel Protective Coating		Underwater	04/06/2017	999 SF	0	0	999	0
		Migrated Values		999 SF	0	0	999	0
	Notes: [2016] Migrator assumed quantity of 999 SF and estimated the condition states.							
215	Reinforced Concrete Abutment	Underwater	04/06/2017	109 LF	99	10	0	0
		Migrated Values		109 LF	99	10	0	0
	Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:30 CS2:10 CS3:0 CS4:0). Several vert. hairline cracks each abut. Water leaking thru at SE & NE corners.							
	Wingwall notes: No change. 2015: Spall @ end SW WW.							
234	Reinforced Concrete Pier Cap	Underwater	04/06/2017	69 LF	69	0	0	0
		Migrated Values		69 LF	69	0	0	0
	Notes: No change.							

BRIDGE 33506 CSAH 8 OVER KNIFE RIVER

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
313	Fixed Bearing	Underwater	04/06/2017	20 EA	16	4	0	0
		Migrated Values		20 EA	16	4	0	0
Notes: (Counted 10 fixed bearings) 2015: Pack rust SE, NE, & SW bearings, also 2nd in from SE.								
330	Metal Bridge Railing	Underwater	04/06/2017	223 LF	0	223	0	0
		Migrated Values		223 LF	0	223	0	0
Notes: No change. 2015: Corrosion on bottom portion of all railings.								
	515 - Steel Protective Coating	Underwater	04/06/2017	999 SF	999	0	0	0
		Migrated Values		999 SF	999	0	0	0
Notes: [2016] Migrator assumed CS1 and a quantity of 999 SF.								
800	Critical Deficiencies or Safety Hazards	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION. None.								
810	Concrete Decks - Cracking & Sealing	Underwater	04/06/2017	0 LF	0	0	0	0
		Migrated Values		0 LF	0	0	0	0
Notes: Numerous areas of cracks & delaminations. 2015: Moderate size cracks & moderate density.								
822	Bituminous Approach Roadway	Underwater	04/06/2017	2 EA	2	0	0	0
		Migrated Values		2 EA	2	0	0	0
Notes: 2015: Cracks in Bit. next to Br. ends need repair.								
855	Secondary Members (Superstructure)	Underwater	04/06/2017	4 EA	0	4	0	0
		Migrated Values		4 EA	0	4	0	0
Notes: 2015: Item for Pier Bracing. Some areas of peeling & rust.								
880	Impact Damage	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: No change.								
883	Concrete Shear Cracking	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to monitor the presence of shear cracking on concrete elements. Pay particular attention to the concrete pier caps.								
885	Scour	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: None.								
891	Other Bridge Signing	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Signs Required: Horizontal Clearance SE delineator is damaged. 2015: All guardrail markers & delineators are in place & in good cond.								
892	Slopes & Slope Protection	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Both slopes need riprap, severe erosion. 2015: No undermining.								

BRIDGE 33506 CSAH 8 OVER KNIFE RIVER

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
893	Guardrail	Underwater	04/06/2017	1 EA	0	1	0	0
		Migrated Values		1 EA	0	1	0	0
Notes: SE end had traffic impact, and has been repaired. 2015: NW end has impact damage 24', 4 posts twisted, plastic spacers broke, & railing bent.								
894	Deck & Approach Drainage	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: 2015: Good cond.								
895	Sidewalk, Curb, & Median	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Numerous cracks & staining on both sides. 2015: Minor spalling around drains.								
900	Protected Species	Underwater	04/06/2017	1 EA	1	0	0	0
		Migrated Values		1 EA	1	0	0	0
Notes: Use this element to track the presence of protected species living on this structure.								

General Notes: PONTIS inspection comments -1999 - Structure remains in good condition. Slab has superficial cracks, but no structural problems. Underside of slab has efflorescence in less than 2% of surface. Remove debris from south pier. Riprap is needed on abutment slopes. Old abutment piling and concrete exposed due to loss of riprap. Both piers need to have h-piling and sway braces painted. Concrete abutments & concrete pier caps in good condition. No cracks or deterioration. 2001 inspection - No change in structures condition. All steel should be painted. All concrete should have a new pearl gray finish applied to it. Also riprap abutment slopes. 2003 inspection - Superficial cracks in slab; but no problems structurally. Efflorescence in less than 2% of slab. All concrete is sound and could have a new pearl gray finish applied to it. Abutments and pier caps are solid, no cracks. Both piers need painting. Remove excess gravel from slab. Riprap is needed on both abutment slopes. 2005 - Abutment and pier concrete members are in good condition. Pier caps are okay. Both piers need to be brushed and repainted. The concrete slab has popouts throughout. The superficial cracks in slab remain the same. Riprap is needed on both abutment slopes. Signs are okay. Remove debris from south pier. NE anchor bolt assembly is corroded but still functioning as intended. 2007 inspection - No change from previous inspection. Unable to inspect for scour at this time. Will complete inspection in spring after iceout and forward info to MN/DOT at that time. 8-5-08 Minor scour at SW pier. Will continue to monitor. 2009 - Pop outs in concrete slab have been patched with bituminous material. All other concrete is sound. Less than 2% efflorescence underside of slab. Riprap needed on both abutment slopes. Remove debris from south pier. ET guardrail in good condition. Signs okay.
2011 - Pop-outs in deck slab have been patched. Found cracks in deck underside that are more evident this year with efflorescence from them. The southeast corner under the deck slab has some concrete loss exposing a rusted rebar in the under side deck. Abutments and pier concrete are in good condition. Steel bearing pads on the abutments are corroded. Riprap is needed on abutment slopes. Some debris on south side of pier one should be removed. Pier steel needs repainted. Deck drains, railings, guardrail, and signs are in good condition. No scour present at the time of inspection. South expansion joint is missing steel angle iron in the middle.
2013 - Same as 2011. Except no debris S. side pier one. See notes for each element.
2015: Several items added or deleted per recommendation of 2014 NBIS comp. report. Br. is in good cond. with the exception of deck. Lots of cracks spalls & delaminations. See the list we've compiled. Easterly 4 piling on N. pier have impact damage @ base.

58. Deck NBI: No change.
2015: Numerous areas of cracks & delaminations.

36A. Brdg Railings NBI:

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail Terminal NBI:

59. Superstructure NBI: No change.

60. Substructure NBI: No change.
[2017] Underwater Inspection - Moderate paint failure and surface corrosion on steel H-piles.

61. Channel NBI: No change.

62. Culvert NBI:

71. Waterway Adeq NBI: No change

BRIDGE 33506 CSAH 8 OVER KNIFE RIVER

ELEM NBR	ELEMENT NAME	REPORT TYPE	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
-------------	--------------	-------------	------------	----------	-------------	-------------	-------------	-------------

72. Appr Roadway No change.
Alignment NBI:

Inspector's Signature

Reviewer's Signature

Pictures



Photo 1 - East Elevation Looking Northwest



Photo 2 - Pier 1 Looking Northwest



Pictures



Photo 3 - Pier 1 Looking South



Photo 4 - Pier 2 Looking South



SOUNDING PLAN

Legend


- 6.2 Sounding Depth from Waterline (4/6/2017)
- I H-pile
- Timber Debris
- Timber Log

GENERAL NOTES:

1. Piers 1 and 2 were inspected underwater.
2. At the time of inspection on April 6, 2017 the waterline was located approximately 11.1 feet below the top of the pier cap at the downstream end of Pier 1. This corresponds with a waterline elevation of 176.7 feet based on design drawings from 1966.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.


INSPECTION NOTES

- 1 Channel bottom material consisted of cobbles, up to 2 feet in diameter.
- 2 Steel H-piles typically exhibited paint system failure from 2 feet above the waterline to the channel bottom.
- 3 Heavy timber debris, up to 1 foot diameter, and garbage have accumulated between Pier 1 and the south shoreline. Garbage includes a large corrugated steel pipe with a steel box attached, photos included in inspection report.
- 4 Submerged log, up to 16 inches in diameter, observed from the upstream nose of Pier 2 extending halfway into the main span channel.




TYPICAL END VIEW OF PIERS

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 33506 OVER THE KNIFE RIVER DISTRICT 3, KANABEC COUNTY		
INSPECTION AND SOUNDING PLAN		
Drawn By: JMF	COLLINS ENGINEERS	Date: APRIL 2017
Checked By: CRS	<small>1599 Selby Avenue Suite 206 St. Paul, MN 55104 (651) 646-8502 www.collinsengr.com</small>	Scale: NTS
Code: 63-9687		Figure No.: 1



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 33506 OVER THE KNIFE RIVER DISTRICT 3, KANABEC COUNTY		
INSPECTION AND SOUNDING PLAN		
Drawn By: JMF	COLLINS ENGINEERS <small>1599 Selby Avenue Suite 206 St. Paul, MN 55104 (651) 646-8502 www.collinsengr.com</small>	Date: APRIL 2017
Checked By: CRS		Scale: 1"=20'
Code: 63-9687		Figure No.: 1