

2017 UNDERWATER BRIDGE INSPECTION REPORT



BRIDGE # 08527 CSAH 13 over MINNESOTA RIVER

DISTRICT: District 7

COUNTY: Brown

CITY/TOWNSHIP: MILFORD

STATE: Minnesota

Date of Inspection: 05/03/2017

Equipment Used:

Owner: County Highway Agency

Inspected By: Stuber, Cory

Report Written By: Cory Stuber

Report Reviewed By:

Final Report Date:



TABLE OF CONTENTS

| | PAGE NUMBER |
|----------------------------------|--------------------|
| UNDERWATER SUMMARY | 3 |
| UNDERWATER INSPECTION | 4 |
| UNDERWATER INSPECTION PROCEDURES | 6 |
| STRUCTURE INVENTORY | 7 |
| ELEMENTS | 8 |
| PICTURES | 12 |
| DRAWINGS | 15 |

UNDERWATER INSPECTION

REPORT SUMMARY

The substructure units inspected at Bridge No. 08527, Piers 1 - 2, and Bent 2, were found to be in good condition with no defects of structural significance observed. The concrete of the Piers was generally smooth and sound. A moderate accumulation of timber debris was noted at the channel bottom at the upstream end of Pier 2. A localized scour depression was observed at the upstream end of Pier 2, with a 5 foot radius and up to a 2 foot depth. Aside from the localized area of scour around Pier 2, the channel bottom around the substructure units has no other notable defects.

INSPECTION FINDINGS

- (A) Channel bottom material consisted of silty sand with 1.5 feet of maximum probe rod penetration.
- (B) Minor scour depression observed, with a 5 foot radius and a 1 to 2 foot depth, at the upstream end of Pier 2.
- (C) Moderate accumulation of timber debris consisting of 1 foot diameter and smaller logs and branches was observed at the upstream end of Pier 2 from the channel bottom up 5 feet.

RECOMMENDATIONS

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of sixty (60) months.

Contractor: Collins Engineers, Inc.

Contractor Job Number: 9687

UNDERWATER INSPECTION

1. BRIDGE DATA

Bridge #: 08527
Feature Intersected: MINNESOTA RIVER
Facility Carried: CSAH 13
District: District 7
County: 008 - Brown

Bridge Description:

The superstructure consists of eight spans supported by a combination of reinforced concrete column piers, reinforced concrete pile bents with hinged pier walls and reinforced concrete abutments. The substructure units are designated as the South Abutment, Bents 1 - 2, Piers 1 - 3, Bents 3 - 4, and the North Abutment.

2. INSPECTION DATA

Professional Engineer/Team Leader: Cory Stuber, P.E.
Inspection Diver: Garrett Owens, P.E.
Date of Underwater Inspection: 05/03/2017
Weather Conditions: Rainy, 60°F
Underwater Visibility (feet): 0.5
Waterway Velocity (ft/sec): 2.0

3. SUBSTRUCTURE INSPECTION DATA

Substructure(s) Inspected: Bent 2, Piers 1 - 2

General Shape:

Piers 1 - 2 consist of a reinforced concrete column pier with web walls, founded on a pile supported reinforced concrete footing. Pier 1 has two concrete columns connected with a reinforced concrete web wall supporting a concrete pier cap, and Pier 2 has four concrete columns connected with a reinforced concrete web wall. Bent 2 consists of a pile supported reinforced concrete pier cap with a hinged pier wall.

Maximum Water Depth at Substructure(s) Inspected (feet): 19.9

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap at the downstream end of Pier 1.
Waterline Elevation (feet): 798.0
Description: The waterline was approximately 12.0 feet below reference.

5. NBIS CODING INFORMATION

(Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code: 7
Item 61: Channel and Channel Protection: Code: 6
Item 62: Culvert: Code:

Item 92B: Underwater Inspection: Code: Y 48 05/2017

Item 113: Scour Critical Bridge: Code: I

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

Yes No (Mark your selection with an X)

6. STRUCTURAL ELEMENT CONDITION RATING

| ELEM # | Element Description | Quantity | Unit | Conditions | | | |
|--------|-------------------------------|----------|------|------------|-----|-----|-----|
| | | | | CS1 | CS2 | CS3 | CS4 |
| 205 | Reinforced Concrete Column | 6 | EA | 6 | | | |
| 210 | Reinforced Concrete Pier Wall | 54 | LF | 54 | | | |
| 885 | Scour | 1 | EA | | 1 | | |
| | | | | | | | |
| | | | | | | | |

UNDERWATER INSPECTION

INSPECTION PROCEDURES

The routine underwater inspection of Bridge 08527 (CSAH 13 over the Minnesota River) was completed on May 3, 2017. The underwater inspection was conducted from a 14 ft boat. The inspection was conducted by a team consisting of a PE-Diver with a valid MnDOT Team Leader certification, a backup diver and a dive tender. The inspection utilized commercial dive equipment and techniques (SSA and/or SCUBA) in accordance with OSHA regulations. Profiles were taken along the upstream and downstream faces of the bridge and around the periphery of substructure units to determine the presence, location and area of scour.

The bridge elements inspected consisted of two reinforced concrete column piers and one pile bent pier with hinged pier wall. According to the bridge inventory or design drawings, Piers 1 - 2 and Bent 2 were founded on pile supported reinforced concrete footings. Inspection procedures followed FHWA guidance and the MnDOT Bridge and Structure Inspection Program Manual with channel bottom probing to search for foundations. The routine underwater inspection frequency is recommended to remain at a maximum of 60 months based on those findings and risk factors. Also, inspection procedures should continue to follow the above approach and standard guidance with 100% Level I and 10% Level II intensity efforts.

Minnesota Structure Inventory Report

Bridge ID: 08527

CSAH 13 over MINNESOTA RIVER

Date: 05/18/2017

| + GENERAL + | + ROADWAY + | + INSPECTION + | | | | | | | | | | | | | | | | | | | | |
|--|---|--|------------|-----|------|------|-----------------------|--|--|--|-------------------|--|----|------------|----------------------|--|--|--|--------------------|--|--|--|
| Agency Br. No. Crew District 07 Maint. Area County 008 - Brown City Township 08010 - MILFORD Desc. Loc. AT N CO LINE Sect., Twp., Range 1 - 110N - 31W Latitude 44 ° 21 ' 41.80 " Longitude -94 ° 29 ' 53.35 " Custodian 02 - County Highway Agency Owner 02 - County Highway Agency BMU Agreement Year Built 1987 MN Year Reconstructed FHWA Year Reconstructed MN Temporary Status Bridge Plan Location 3 - COUNTY Date Opened to Traffic On - Off System 1 - ON Legislative District 21B Potential ABC 2 - N/A | Bridge Match ID (TIS) 0 Roadway O/U Key Route On Structure Route Sys 04 - CSAH Number 13 Roadway Name or Description CSAH 13 Level of Service 1 - MAINLINE Roadway Type 2 - 2-way traffic Control Section (TH Only) Reference Point Detour Length 10.0 mi. Lanes ON 2 UNDER 0 ADT 2100 YEAR 2005 HCA DT ADTT % Functional Class 07 - Rural - Major Collector | Userkey 48 Structurally Deficient N Functionally Obsolete N Sufficiency Rating 96.4 Routine Inspection Date 11/03/2016 Routine Inspection Frequency 24 Inspector Name Stuber, Cory Status A - Open | | | | | | | | | | | | | | | | | | | | |
| | | + NBI CONDITION RATINGS + | | | | | | | | | | | | | | | | | | | | |
| | | Deck 6 Unsound Deck % Superstructure 7 Substructure 7 Channel 6 Culvert N | | | | | | | | | | | | | | | | | | | | |
| | + RDWY DIMENSIONS + | + NBI APPRAISAL RATINGS + | | | | | | | | | | | | | | | | | | | | |
| | If Divided NB-EB SB-WB Roadway Width 40.00 ft. ft. Vertical Clearance ft. ft. Max. Vert. Clear. ft. ft. Horizontal Clear. ft. ft. Lateral Clearance ft. ft. Appr. Surface Width 40.0 ft. Bridge Roadway Width 40.0 ft. Median Width On Bridge ft. | Structure Evaluation 7 Deck Geometry 6 Underclearances N Waterway Adequacy N Approach Alignment 8 | | | | | | | | | | | | | | | | | | | | |
| + STRUCTURE + | + MISC. BRIDGE DATA + | + SAFETY FEATURES + | | | | | | | | | | | | | | | | | | | | |
| Service On 1 - Highway Service Under 5 - Waterway Main Span Type 4 - Steel Continuous Main Span Design 01 - Beam Span Main Span Detail Appr. Span Type Appr. Span Design Appr. Span Detail Skew 0 Culvert Type Barrel Length Cantilever ID F - Friction Hinge Number of Spans MAIN: 8 APPR: 0 TOTAL: Main Span Length 145.0 ft. Structure Length 598.6 ft. Deck Width (Out-to-Out) 43.3 ft. Deck Material 1 - Concrete Cast-in-Place Wear Surf Type 1 - Monolithic Concrete Wear Surf Install Year Wear Course/Fill Depth 0.00 ft. Deck Membrane 0 - None Deck Rebars 1 - Epoxy Coated Reinforcing Deck Rebars Install Year 1987 Structure Area (Out-to-Out) 25919 sq. ft. Roadway Area (Curb-to-Curb) 23939 sq. ft. Sidewalk Width 50A. Lt 0.00 ft. 50B. Rt 0.00 ft. Curb Height Lt 0.00 ft. Rt 0.00 ft. Rail Type Lt 22 Rt 22 | Structure Flared 0 - No flare Parallel Structure N - No parallel structure Field Conn. ID 4 - Bolted Abutment Foundation (Material/Type) 3 - FTG PILE Pier Foundation (Material/Type) 3 - FTG PILE Historic Status 5 - Not eligible | Bridge Railing 1 - MEETS STANDARDS GR Transition 0 - SUBSTANDARD Appr. Guardrail 0 - SUBSTANDARD GR Termini 0 - SUBSTANDARD | | | | | | | | | | | | | | | | | | | | |
| | + PAINT + | + IN DEPTH INSP. + | | | | | | | | | | | | | | | | | | | | |
| | Year Painted 1987 Unsound Paint % Painted Area sq. ft. Primer Type D - Organic Zinc - 3309 Finish Type H - Vinyl | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th style="text-align: center;">Y/N</th> <th style="text-align: center;">Freq</th> <th style="text-align: center;">Date</th> </tr> </thead> <tbody> <tr> <td>Frac. Critical</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Underwater</td> <td></td> <td style="text-align: center;">60</td> <td style="text-align: center;">05/03/2017</td> </tr> <tr> <td>Pinned Asbly.</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Spec. Feat.</td> <td></td> <td></td> <td></td> </tr> </tbody> </table> | | Y/N | Freq | Date | Frac. Critical | | | | Underwater | | 60 | 05/03/2017 | Pinned Asbly. | | | | Spec. Feat. | | | |
| | Y/N | Freq | Date | | | | | | | | | | | | | | | | | | | |
| Frac. Critical | | | | | | | | | | | | | | | | | | | | | | |
| Underwater | | 60 | 05/03/2017 | | | | | | | | | | | | | | | | | | | |
| Pinned Asbly. | | | | | | | | | | | | | | | | | | | | | | |
| Spec. Feat. | | | | | | | | | | | | | | | | | | | | | | |
| | + BRIDGE SIGNS + | + WATERWAY + | | | | | | | | | | | | | | | | | | | | |
| | Posted Load 0 - Not Required Traffic 0 - Not Required Horizontal 1 - Object Markers Vertical N - Not Applicable | Drainage Area (sq. mi.) 9530.0 Waterway Opening (sf.) 8600 Navigation Control 0 - No nav. control on Pier Protection Nav. Clr. (ft.) Vert. 0.0 Horiz. 0.0 Nav. Vert. Lift Bridge Clear. (ft.) MN Scour Code I - LOW RISK Year 1991 | | | | | | | | | | | | | | | | | | | | |
| | | + CAPACITY RATINGS + | | | | | | | | | | | | | | | | | | | | |
| | | Design Load 5 - HS 20 Operating Rating 2 - HS TRUCK 34.0 Inventory Rating 2 - HS TRUCK 24.0 Posting VEH: SEMI: DBL: Rating Date 4/23/1991 Overweight Permit Codes A N - N/A B N - N/A C N - N/A | | | | | | | | | | | | | | | | | | | | |

MINNESOTA BRIDGE INSPECTION REPORT

05/19/2017

BRIDGE 08527 CSAH 13 OVER MINNESOTA RIVER

| | | |
|---|--|---|
| County: Brown | Location: AT N CO LINE | Length: 598.6 ft. |
| City: | Route: 04 - CSAH 13 Ref. Pt.: 018+00.868 | Deck Width: 43.3 ft. |
| Township: 08010 - MILFORD | Control Section: | Rdwy. Area/ Pct. Unsnd: 23939 sq. ft. / % |
| Section: 1 Township: 110N Range: 31W Maint. Area: | | Paint Area/ Pct. Unsnd: sq. ft. / % |
| Span Type: 4 - Steel Continuous 2 - Stringer/Multi- beam or Girder | Local Agency Bridge Nbr.: | Culvert: N/A |
| List: | | Postings: |
| NBI Deck: 6 Super: 7 Sub: 7 Chan: 6 Culv: N | | |
| | Open, Posted, Closed: A - Open | |
| | MN Scour Code: I - LOW RISK | |

| | |
|--|-------------------------------------|
| Appraisal Ratings - Approach: 8 Waterway: N | Unofficial Structurally Deficient N |
| Required Bridge Signs - Load Posting: 0 - Not Required | Unofficial Functionally Obsolete N |
| Horizontal: 1 - Object Markers | Unofficial Sufficiency Rating 96.4 |
| Traffic: 0 - Not Required | |
| Vertical: N - Not Applicable | |

| ELEM NBR | ELEMENT NAME | REPORT TYPE | INSP. DATE | QUANTITY | QTY CS 1 | QTY CS 2 | QTY CS 3 | QTY CS 4 |
|---------------------------------------|--|-------------|------------|----------|----------|----------|----------|----------|
| 12 | Reinforced Concrete Deck | Underwater | 05/03/2017 | 25919 SF | 25401 | 0 | 518 | 0 |
| | | Routine | 11/03/2016 | 25919 SF | 25401 | 0 | 518 | 0 |
| | Notes: Efflorescence mainly in the forth and fifth spans. | | | | | | | |
| 510 - Wearing Surfaces | | Underwater | 05/03/2017 | 23939 SF | 23460 | 0 | 479 | 0 |
| | | Routine | 11/03/2016 | 23939 SF | 23460 | 0 | 479 | 0 |
| | Notes: Top of Concrete Deck with Epoxy Reinforcement Notes: 2015-2016 Cracks in surface of deck. | | | | | | | |
| 107 | Steel Open Girder/Beam | Underwater | 05/03/2017 | 3294 LF | 0 | 3294 | 0 | 0 |
| | | Routine | 11/03/2016 | 3294 LF | 0 | 3294 | 0 | 0 |
| | Notes: Weathering steel has minor dusting throughout structure. No section loss found. 2015-2016 Flaking of paint at cantilever ends. | | | | | | | |
| 515 - Steel Protective Coating | | Underwater | 05/03/2017 | 24705 SF | 0 | 24705 | 0 | 0 |
| | | Routine | 11/03/2016 | 24705 SF | 0 | 24705 | 0 | 0 |
| | Notes: 2016 Minor dusting of surface peeling paint at cantilever joints. | | | | | | | |
| 205 | Reinforced Concrete Column | Underwater | 05/03/2017 | 19 EA | 19 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 19 EA | 19 | 0 | 0 | 0 |
| | Notes: Staining of concrete from water infiltration through joints. | | | | | | | |
| 210 | Reinforced Concrete Pier Wall | Underwater | 05/03/2017 | 125 LF | 125 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 125 LF | 125 | 0 | 0 | 0 |
| | Notes: Staining of concrete from water infiltration through joints. | | | | | | | |
| 215 | Reinforced Concrete Abutment | Underwater | 05/03/2017 | 121 LF | 121 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 121 LF | 121 | 0 | 0 | 0 |
| | Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:40 CS2:0 CS3:0 CS4:0). | | | | | | | |
| | Wingwall notes: Erosion under south wing walls. | | | | | | | |
| 234 | Reinforced Concrete Pier Cap | Underwater | 05/03/2017 | 302 LF | 302 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 302 LF | 302 | 0 | 0 | 0 |
| 300 | Strip Seal Expansion Joint | Underwater | 05/03/2017 | 95 LF | 95 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 95 LF | 95 | 0 | 0 | 0 |
| | Notes: Gland torn and falling out. Gland replaced fall 2008 in excellent shape at time of inspection. 2013-2016 gland intact but could be cleaned out. | | | | | | | |

BRIDGE 08527 CSAH 13 OVER MINNESOTA RIVER

| ELEM NBR | ELEMENT NAME | REPORT TYPE | INSP. DATE | QUANTITY | QTY CS 1 | QTY CS 2 | QTY CS 3 | QTY CS 4 |
|--|---|-------------|------------|----------|----------|----------|----------|----------|
| 301 | Pourable Joint Seal | Underwater | 05/03/2017 | 95 LF | 95 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 95 LF | 95 | 0 | 0 | 0 |
| 311 | Movable Bearing | Underwater | 05/03/2017 | 16 EA | 0 | 16 | 0 | 0 |
| | | Routine | 11/03/2016 | 16 EA | 0 | 16 | 0 | 0 |
| Notes: Corrosion and flaking rust on pins and nuts. | | | | | | | | |
| 313 | Fixed Bearing | Underwater | 05/03/2017 | 28 EA | 0 | 28 | 0 | 0 |
| | | Routine | 11/03/2016 | 28 EA | 0 | 28 | 0 | 0 |
| Notes: Corrosion on pins and nuts . | | | | | | | | |
| 331 | Reinforced Concrete Bridge Railing | Underwater | 05/03/2017 | 1197 LF | 0 | 1197 | 0 | 0 |
| | | Routine | 11/03/2016 | 1197 LF | 0 | 1197 | 0 | 0 |
| Notes: Intermideate cracking between deflection joints with minor spalls. No evidence of rebar corrosion during this inspection 12-15-04. 2015 Staining on railings, map cracking on face of rail no delamination found. | | | | | | | | |
| 800 | Critical Deficiencies or Safety Hazards | Underwater | 05/03/2017 | 1 EA | 1 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 1 | 0 | 0 | 0 |
| Notes: NO CRITICAL FINDINGS OBSERVED DURING THE LAST INSPECTION. | | | | | | | | |
| 810 | Concrete Decks - Cracking & Sealing | Underwater | 05/03/2017 | 0 LF | 0 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 0 LF | 0 | 0 | 0 | 0 |
| Notes: 2015 Cracks throughout deck some signifacant in size, many cracks holding water. | | | | | | | | |
| 822 | Bituminous Approach Roadway | Underwater | 05/03/2017 | 2 EA | 0 | 2 | 0 | 0 |
| | | Routine | 11/03/2016 | 2 EA | 0 | 2 | 0 | 0 |
| Notes: 2015-2016 Minors ettlement both approaches, north approach has been seal coated and fog sealed. | | | | | | | | |
| 855 | Secondary Members (Superstructure) | Underwater | 05/03/2017 | 1 EA | 1 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 1 | 0 | 0 | 0 |
| 885 | Scour | Underwater | 05/03/2017 | 1 EA | 0 | 1 | 0 | 0 |
| Notes: [2017] Underwater Inspection - Minor scour depression with a 5 foot radius and up to 2 foot depth at the upstream end of Pier 2. | | | | | | | | |
| 891 | Other Bridge Signing | Underwater | 05/03/2017 | 1 EA | 1 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 1 | 0 | 0 | 0 |
| 892 | Slopes & Slope Protection | Underwater | 05/03/2017 | 1 EA | 0 | 0 | 0 | 1 |
| | | Routine | 11/03/2016 | 1 EA | 0 | 0 | 0 | 1 |
| Notes: Erosion under wing walls all four corners, erosion under abutment walls. 2013-2015 much of the rip-rap is missing possible throw into the river. | | | | | | | | |
| 893 | Guardrail | Underwater | 05/03/2017 | 1 EA | 1 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 1 | 0 | 0 | 0 |
| Notes: 2015-2016 Turn down guardrail, timbers are in good shape. | | | | | | | | |
| 894 | Deck & Approach Drainage | Underwater | 05/03/2017 | 1 EA | 0 | 1 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 0 | 1 | 0 | 0 |
| Notes: 2016 Road draining and eroding at south wingwalls. Drains creating erosion of soils under bridge. | | | | | | | | |

BRIDGE 08527 CSAH 13 OVER MINNESOTA RIVER

| ELEM NBR | ELEMENT NAME | REPORT TYPE | INSP. DATE | QUANTITY | QTY CS 1 | QTY CS 2 | QTY CS 3 | QTY CS 4 |
|-------------|-------------------|-------------|------------|----------|-------------|-------------|-------------|-------------|
| 900 | Protected Species | Underwater | 05/03/2017 | 1 EA | 1 | 0 | 0 | 0 |
| | | Routine | 11/03/2016 | 1 EA | 1 | 0 | 0 | 0 |

Notes: Use this element to track the presence of protected species living on this structure.

General Notes: *Located in section 1-110-31

96,98) Grease all bearing devices and rockers.
 N. abutment east bearing missing nut & key.
 S. abutment west bearing clean & paint.

126) Minor cracking and staining on underside of deck.

90) Clean expansion joints. Gland is torn in several places.

99) Bit. surface cracking and settling, need to seal and patch.

185) Erosion around SW wing wall causing settlement of the roadway

05/28/96 Snooper Inspection. L. Kilmer and P. Madden did closeup inspection of underside of deck, bearing assemblies and cantiliver connections of girders.

90) Expansion glands at both cantiliver joints are punctured.

96,98) Grease fittings are not provided on bearing assemblies. All appear to be functioning as intended.

7,50) No cracks, loose bolts or other problems were noted in girders or secondary steel members.

1999 Same as 1998 insp.

2000

90) Expansion joints are severly torn and should be replaced.

58. Deck NBI:

36A. Brdg Railings NBI:

36B. Transitions NBI:

36C. Appr Guardrail NBI:

36D. Appr Guardrail
 Terminal NBI:

59. Superstructure NBI:

60. Substructure NBI:

61. Channel NBI: [2017] Underwater Inspection - Channel rating changed to 6 due to presence of scour at Pier 2.

62. Culvert NBI:

71. Waterway Adeq NBI:

72. Appr Roadway
 Alignment NBI:

| ELEM NBR | ELEMENT NAME | REPORT TYPE | INSP. DATE | QUANTITY | QTY CS 1 | QTY CS 2 | QTY CS 3 | QTY CS 4 |
|-------------|-----------------------|-------------|------------|----------|-------------|-------------|----------------------|-------------|
| | Inspector's Signature | | | | | | Reviewer's Signature | |

Pictures



Photo 1 - Downstream Elevation Looking Southeast



Photo 2 - Upstream Elevation Looking Northeast

Pictures



Photo 3 - Bent 2 Looking Northwest




Photo 4 - Pier 1 Looking Northwest

Pictures



Photo 5 - Pier 2 Looking Southwest



SOUNDING PLAN

Legend

- 2.0 Sounding Depth (5/3/2017)
- 5.2 Sounding Depth (9/12/2012)
- Timber Debris
- Scour Depression

Note:


All soundings based on 2017 waterline location.

GENERAL NOTES:

1. Piers 1 and 2, and Bent 2 were inspected underwater.
2. At the time of inspection, on May 3, 2017, the waterline was located approximately 12.0 feet below the top of the pier cap of Pier 1 on the downstream end. This corresponds to a waterline elevation of 798.0.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.


INSPECTION NOTES:

- ① Channel bottom material consisted of silty sand with 1.5 feet of maximum probe rod penetration.
- ② Minor scour depression observed, with a 5 foot radius and a 1 to 2 foot depth, at the upstream end of Pier 2.
- ③ Moderate accumulation of timber debris consisting of 1 foot diameter and smaller logs and branches was observed at the upstream end of Pier 2 from the channel bottom up 5 feet.




TYPICAL END VIEW OF EACH PIER SECTION

| | | |
|---|---|----------------|
| MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION | | |
| STRUCTURE NO. 08527 CSAH 13 OVER THE MINNESOTA RIVER DISTRICT 7, BROWN COUNTY | | |
| INSPECTION AND SOUNDING PLAN | | |
| Drawn By: JMF | COLLINS ENGINEERS | Date: MAY 2017 |
| Checked By: CRS | <small>1599 Selby Avenue Suite 206 St. Paul, MN. 55104 (651) 646-8502 www.collinsengr.com</small> | Scale: NTS |
| Code: 63-9687 | | Figure No.: 1 |



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

| | | |
|---|---|----------------|
| MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION | | |
| STRUCTURE NO. 08527 CSAH 13 OVER THE MINNESOTA RIVER DISTRICT 7, BROWN COUNTY | | |
| UPSTREAM AND DOWNSTREAM FASCIA PROFILES | | |
| Drawn By: JMF | COLLINS ENGINEERS <small>1599 Selby Avenue Suite 206 St. Paul, MN, 55104 (651) 646-8502 www.collinsengr.com</small> | Date: MAY 2017 |
| Checked By: CRS | | Scale: 1"=40' |
| Code: 63-9687 | | Figure No.: 2 |