Pipe Materials

In HydInfra



Johnston-Fargo Photo Credits

- photo 0680- galvanized (Zinc coating) has information stenciled on the coated steel, date, heat #, manufacturer, ASTM & AASHTO designations. (50 years life expectancy)
- photo 0681- aluminized T2 has same information stenciled on coated steel, date, heat
 #, manufacturer, ASTM & AASHTO desginations.
- photo 0688- polymeric has same information stenciled on coated steel, date, heat #, manufacturer, ASTM & AASHTO desgination.
- photo 0669- polymeric coated stencil -
- photo 0670- 100 years (plus) service life on the poly coated steel, comes in annular(rivited), spiral & spiral rib 16ga, 14ga, 12ga.
- photo 0672-75 years (plus) service life on the aluminized type 2, comesin annular(rivited), spiral & spiral rib 16ga, 14ga, 12ga, & 10ga.
- photo 0674 50 years (plus) stock annual (rivited) pipe
- photo 0673 aluminized Type 2 pipe in spiral corruagtion
- photo 0677 aluminized Type 2 pipe in spiral rib & galvanized pipe in sprial corrugation (compare differnt coatings & corrugations)
- photo 0679 galvanized coating spiral corrugation
- photo 0678 aluminized type 2- spiral rib corrugation
- photo 0675 galvanized annular

Galvinized Steel



photo 0680- galvanized (Zinc coating) has information stenciled on the coated steel, date, heat #, manufacturer, ASTM & AASHTO designations. (50 years life expectancy)




photo 0679 - galvanized coating spiral corrugation

photo 0675 - galvanized annular




Galvanized Steel

Old pipe with new extension



Steel Plate

Note the Bolts



Polymeric-coated Steel



photo 0688- polymeric has same information stenciled on coated steel:

date, heat #, manufacturer, ASTM & AASHTO designation



photo 0669- polymeric coated stencil

photo 0670- 100 years (plus) service life on the poly coated steel, comes in annular(rivited), spiral & spiral rib - 16ga, 14ga, 12ga.



Aluminized Steel



photo 0681- aluminized T2 has same information stenciled on coated steel, date, heat #, manufacturer, ASTM & AASHTO desginations.



photo 0672 -75 years Manufacturer's projected service life on the aluminized type 2, comes in annular(rivited), spiral & spiral rib - 16ga, 14ga,12ga, & 10ga.

photo 0678 - aluminized type 2- spiral <u>rib</u> corrugation

photo 0673 - aluminized Type 2
pipe - in spiral corrugation



More Aluminized Steel




photo 0677 - aluminized Type 2 pipe in spiral rib & galvanized pipe in sprial corrugation (compare differnt coatings & corrugations)




Wooden Pipe!

District 1 in Duluth
State Highway MN 23









Concrete Pipe – Corrugated!




Corrugated Concrete Pipe -- I 35 in Duluth (photo from Pat LaMourea)

Plastic Pipe

- Smooth Plastic HDPE or PVC
- Corrugated Plastic -- HDPE

Plastic Pipe



"Smooth Plastic" dual wall HDPE has slight corrugations. PVC (no photo available) would also be "Smooth Plastic"

Plastic Pipe

Corrugated Plastic



HDPE -- PVC

HydInfra does not differentiate YET. But will in future.

Pipe Liner Materials

Liner Plastic

■ Not yet in HydInfra: Cured in Place