Michigan's Unbonded Overlay Experience

2011 Terra Pavement Conference February 10, 2011

Michael Eacker Pavement Design Engineer Michigan Department of Transportation

MDOT Mission

"Providing the highest quality integrated transportation services for economic benefit and improved quality of life."

Overview

ECMDOT

- Introduction
- Performance Curve
- Lessons Learned
- Research Project
- Other Concrete Overlays
- Local Agency Work

Introduction

- Michigan DOT has used unbonded concrete overlays to rehabilitate concrete and composite pavements since 1984.
- 23 projects totaling 240+ centerline miles.
 - Two projects in 1984
 - US-23 near Dundee reconstructed in 2003
 - I-96 in Ionia County still in service
 - Remaining 21 projects from 1990 to present



Introduction

- Thickness from 6" to 8"
- Joint spacing has been 27' and 41' for JRCP and 12' for JPCP (1998 to present).
- 1" to variable thick separator layer
 - Started with variable thickness
 - Moved to uniform 1" thickness
 - Moved to drainable HMA in 2003
- 20 year design life
- Life-cycled against rubblize projects

Performance Curve

- Distress Index (DI) is Mich DOT's condition measure for modeling performance
- DI is an increasing scale of points assigned to surface distresses and then indexed to 0.1 mile segments
- DI of 50 is considered to be the time to rehab or reconstruct the pavement
- Pre-maintenance DI points modeled with logistic growth curve

Performance Curve

- Average age and DI drop is found for all maintenance work
- Initial growth curve is adjusted based on maintenance averages
- Result for unbonded overlays:
 - Service life = 21 years including one maintenance cycle

Performance Curve

Pavement Preservation Strategy

Unbonded Concrete Overlay



- Crown correction
 - Existing pavement = parabolic
 - New pavement = 2% cross-slope
- Initially corrected crown with HMA
- HMA separator layer was a fine mix
 - Edge distress due to HMA compaction under traffic
 - Moved to uniform 1" separator layer with crown correction in the concrete

- Poor drainage
 - Water sitting on the separator layer eroding the HMA

EMDOT

Edge distresses







Changed to a drainable HMA interlayer



Make sure drainage path is clear



High side of superelevations very thick
due to crown correction



- Pre-overlay repair work
 - MDOT has traditionally been very aggressive with repairing all distresses in a concrete pavement
 - Found that we don't need to have that same level of repair work for the overlay – could save money without loss of performance
 - Now only the most severe cracks/joints are repaired prior to the overlay

- "Improved Performance of Concrete Overlays"
- Principle Investigator: Dr. Will Hansen, Univ. of Michigan
- Initiated October 2009
- Completion expected May 2012
- Objectives:
 - Forensic study of existing concrete overlay distresses
 - Recommend changes to pavement design and construction practices

- Example of forensic study
 - I-75 near West Branch (built 2003)
 - 5 test sections
 - #1: 10' joint spacing, undoweled, unsealed
 - #2: 10' joint spacing, undoweled, sealed
 - #3: 12' joint spacing, undoweled, unsealed
 - #4: 12' joint spacing, undoweled, sealed
 - #5: 12' joint spacing, doweled, sealed
 - Sections 3 and 4 exhibiting longitudinal cracking and slightly more faulting



- FWD testing, Dipstick[®] profiling device, coring, pavement removal conducted
- Dipstick[®] found substantially more curl or warp at the joints in Sections 3 and 4
- Coring and pavement removal confirmed wet conditions in the HMA separator layer in those sections, and HMA stripping/erosion



 Also placed temperature sensors in various layers of two projects in 2010



- Whitetopping
 - One project on mainline pavement built in 1999
 - 6" w/o fibers, 6" w/fibers, 5" w/fibers, 3" ultra-thin over composite pavement
 - No milling or repair work to existing 4" HMA
 - 10' transverse joint spacing
 - Some longitudinal cracking
 - Very little difference between sections with and without fibers
 - Some materials related distress at joints

- M-46 (cont.)

- Ultra-thin performing poorly
- Large number of 1 meter X 1 meter panels replaced in 2004. Primarily over the edge of the old 20' wide concrete.

- M-46 (cont.)



EMDOT

• Whitetopping (cont.)

- A few intersections
- Rest area parking lot in 2009

Thin Unbonded Overlays

- M-3 (2005) and M-1 (2010) in Detroit
- 4" concrete, 1" separator layer, existing composite pavement (milled 5")
- M-3 had several test sections
 - Sealed and unsealed joints
 - Two different HMA separator layers
 - Drainable
 - Standard dense-graded HMA
 - 5.5' X 5.5' joint spacing

- M-3 (cont.)
 - 200+ drainage/utility structures
 - Many intersections some at extreme angles
 - Joint layout was very difficult
 - Some cracking of panels
 - Many around structures
 - Some shattered areas found to be very thin (<2")
 - At this point, still less than 1% of panels showing distress

Local Agency Work

- Whitetopping
 - 45+ locations
 - First project (1996, Traverse City) still in service; in good condition
 - 96% are still in service; most in good or very good condition
 - Lessons learned:
 - Line up joints in whitetopping with transitions (widening) below
 - Use lower cement content mixtures
 - In summer, spray down milled HMA to cool down and bring to SSD condition

Courtesy: Michigan Concrete Association

Local Agency Work



Local Agency Work

- Thin unbonded overlays
 - 14 projects
 - First project (Coolidge in Royal Oak) still in service; rehabbed (approx 1.5% of project received full depth repairs) for first time in 2008 after 25 years
 - Lessons learned:
 - Use durable (ASR-resistant) mixtures
 - Proper use of expansion joints (needed where Exp. joints located in existing pavement)
 - Spring & fall paving use cold weather protection, heated water, cover with plastic

Courtesy: Michigan Concrete Association

Thanks to:

Ben Krom, MDOT Pavement Selection Engineer Andy Bennett, MDOT CPM Specialist for Scoping Steve Waalkes, Michigan Concrete Association

This presentation utilized information from previous presentations given by these individuals.

Questions????

Michael Eacker eackerm@michigan.gov (517) 322-3474

