

CIP 9Y2 -East Gull Lake Airport

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2013		NO PROJECTS PROGRAMMED	0	0	0					0	1/1/2013
Totals										0	

Summary for Airport = East Gull Lake Airport (1 detail record)

5010 Inspection Remarks:

Last Inspection Year: 2009

Remark Key	Remark	Runway
A110-1	ARPT CLSD WINTERS.	
B110-3	Need license, rules & map posted on bulletin board.	
B110-4	Restrooms and telephone available at driving range and nearby resorts.	
A42	Rwy 13/31 mkd by yellow cones.	RWY 13
A110-02	Watch for vehicles and pedestrians crossing rwy.	
B110-5	Need better fencing.	
B110-6	Bldg on N side of Rwy in 7:1.	
A57	Rwy 13: Trees + 56, 1060 fm, 88R, 18:1 Lower by 4 feet.	
A57	Rwy 31: Trees +14, 103 fm, 132R, 7:1. Lower by 9 feet.	
B57	Rwy 13: Trees 1,000 to 1500 ft fm runway 5 to 10 feet into approach on SW side.	
B57	Rwy 31: Trees within 200 feet along both sides, 15 to 25 feet into approach.	