

CIP 16D -Perham Municipal Airport

| State FY | Fed FY | Description | Funding Rates | | | 2012 -2017 | | | | | Estimated Construction Start Date |
|---------------|--------|--|---------------|------|------|----------------|-------------|----------------|----------------|----------------|-----------------------------------|
| | | | FAA | St | Mun | Project Cost | FAA Funding | State Funding | Local Funding | Other Programs | |
| 2012 | | Snow Plow Truck | 0 | 66.7 | 33.3 | 160,000 | 0 | 106,667 | 53,333 | 0 | 6/5/2012 |
| 2013 | | Snow Blower for Loader | 0 | 66.7 | 33.3 | 40,000 | 0 | 26,668 | 13,332 | 0 | 6/1/2013 |
| 2014 | | Beacon | 0 | 80 | 20 | 5,000 | 0 | 4,000 | 1,000 | 0 | 6/1/2014 |
| 2015 | | Site Prep and Concrete Work for Hangar | 0 | 50 | 50 | 240,000 | 0 | 120,000 | 120,000 | 0 | 6/1/2015 |
| 2016 | | T-Hangar [Loan] | 0 | 80 | 20 | 400,000 | 0 | 320,000 | 80,000 | 0 | 6/1/2016 |
| Totals | | | | | | 845,000 | 0 | 577,335 | 267,665 | 0 | |

Summary for Airport = Perham Municipal Airport (5 detail records)

5010 Inspection Remarks:

Last Inspection Year: 2008

| Remark Key | Remark | Runway |
|------------|---|--------|
| A81 | ACTVT MIRL RY 12/30; PAPI RY 12; REIL AND PAPI RY 30 - CTAF. | |
| A70 | Fuel Avail 24 Hrs w Credit Card. | |
| A110-01 | Ultrlight activity on & invof airport. | |
| A40-12 | /30 1 rwy light missing on SE end at old crosswind. | RWY 12 |
| B57 | Trees in primary surface and approach surface to Runway 30. | |
| A33 | Rwy 12/30 Rough ride, multiple cracks with grass growing in them. | |
| A110-02 | Caution for Helo ops NW corner of Arpt. | |
| A58 | Rwy 12: Trees +5, 100-200 fm end, 110R. | |
| A58 | Rwy 30: Trees +5, 190 fm end, 200L. | |
| B57 | Rwy 30 obstr by 15 ft trees 300 fm end. | |
| A110-03 | GCO AVBL ON FREQ 121.725 THRU ZMP ARTCC AND PNM FSS. | |

Monday, November 21, 2011