

# CIP OTG - Worthington Municipal Airport

State FY	Fed FY	Description	Funding Rates			2012 -2017					Estimated Construction Start Date
			FAA	St	Mun	Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	
2012		SOUTH APRON A RECONSTRUCTION	95	0	5	657,752	624,864	0	32,888	0	10/1/2011
2012		TAXIWAY B JOINT REPAIRS	95	0	5	83,538	79,361	0	4,177	0	10/2/2011
2013		CHEMICAL LOADING PAD & STORAGE BUILDING	0	50	50	134,000	0	67,000	67,000	0	7/1/2012
2013		AIRPORT FENCING	0	70	30	23,000	0	16,100	6,900	0	7/2/2012
2013		TAXIWAY C EXTENSION	95	0	5	1,240,385	1,178,366	0	62,019	0	10/1/2012
2014		AIRPORT SIGN	0	70	30	18,000	0	12,600	5,400	0	7/1/2013
<b>Totals</b>						<b>2,156,675</b>	<b>1,882,591</b>	<b>95,700</b>	<b>178,384</b>	<b>0</b>	

Summary for Airport = Worthington Municipal Airport (6 detail records)

## 5010 Inspection Remarks:

Last Inspection Year: 2010

Remark Key	Remark	Runway
A81	HIRL 11/29 PRESET ON LOW INTST; TO INCR INTST & ACTVT MIRL RY 17/35; REIL RYS 11 & 17 & 35; PAPI RYS 11 & 29 & PAPI RYS 17 & 35; MALSR RY 29 - CTAF.	
A17	FOR SVCS CALL 507-376-9293, AFT HRS CALL 507-360-9959.	
A70	Self service fuel: VISA, MC accepted.	
B57-11	28:1 Trees, should be 34:1.	RWY 11
B110-02	Sent area map and traffic rules 2010.	
B110-03	Rwy 17/35: Hay Bales in primary surface east of runway.	
B110-04	Rwy 17/35 MIRL all white/white. Yellow replaces white last 2000'.	
B40	Rwy 17/35, Visual lighting on Instr Rwy. Reported Mead & Hunt checking into it, 09/2010.	
A40	Rwy 17/35, Visual lightin on Instr Rwy	
B110-01	Rwy 11/29: Crops and Hay Bales in primary surface. Reported Hay Bales removed 09/2010.	

Monday, November 21, 2011