

2108 Alternative Chemical Deicers Specific Gravity – ASTM D1429 (Method D)

Fill hydrometer cylinder with sample and immerse hydrometer. Make sure hydrometer (range of 1.2-1.4) is free floating and not touching the side of cylinder. Once the hydrometer is stable, read / record the specific gravity.