

CIP D00 -Norman County/Ada/Twin Valley Airport

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2012		NEW RUNWAY LIGHTING (pilot controlled)	0	80	20	100,000	0	80,000	20,000	0	6/5/2012
2012		CRACK REPAIR & SEALING (RWY, TXY, APN)	0	80	20	10,000	0	8,000	2,000	0	6/10/2012
2014		PAPI	0	80	20	50,000	0	40,000	10,000	0	6/1/2014
2014		UPDATE ALP	0	80	20	30,000	0	24,000	6,000	0	6/1/2014
2016		APRON AREA TIEDOWN UPDATE	0	80	20	50,000	0	40,000	10,000	0	7/1/2015
2016		T-HANGAR (8 PLACE) - Hangar Loan	0	0	0	350,000	0	0	0	350,000	6/1/2016
Totals						590,000	0	192,000	48,000	350,000	

Summary for Airport = Norman County/Ada/Twin Valley Airport (6 detail records)

5010 Inspection Remarks:

Last Inspection Year: 2010

Remark Key	Remark	Runway
B110-02	Tiedowns not marked. Reported painted.	
B42	No Runway Markings. Reported painted.	
B110-01	Didn't see "new" airport license posted.	
A70	Fuel Available 24 hours with credit card.	
A40	RWY 15/33 serveral lights leaning.	
B40	RWY 15/33 several lights leaning.	
A110-01	Arpt Mgr Work Phone 218-415-0191.	
B110-03	Arpt Mgr Home Phone 218-784-4381.	
B57	RWY 33, Trees, +82', 1805'FM, 480L, 19:1, should be 20:1 (lower 2')	
B57	Rwy 33: Trees +72, 1800 fm rwy end, 150L, 22:1. (not penetrating YET)	

Monday, November 21, 2011