

CIP AQP -Appleton Municipal Airport

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2012		Bituminous Overlay	0	80	20	250,000	0	200,000	50,000	0	6/1/2012
			Totals			250,000	0	200,000	50,000	0	

Summary for Airport = Appleton Municipal Airport (1 detail record)

5010 Inspection Remarks:

Last Inspection Year: 2008

Remark Key	Remark	Runway
A30-04	/22 Closed Winter Months.	RWY 04
A42-04	/22 Mkd with Yellow Cones.	RWY 04
A81	ACTVT MIRL RY 13/31 - CTAF.	
B14	Manager Cell: 500-845-9575	
A110-1	Ultralights on & invof Arpt.	
A33	2 inch cracks in pavement.	
B57	Rwy 31 Obstr by Trees 15:1. Cut 13' off trees or Displ 250'.	