

CIP 9Y0 -Bowstring Airport

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2013		NO PROJECTS PROGRAMMED	0	70	30	0	0	0	0	0	7/1/2012
			Totals			0	0	0	0	0	

Summary for Airport = Bowstring Airport (1 detail record)

5010 Inspection Remarks:

Last Inspection Year: 2009

Remark Key	Remark	Runway
A110-1	ARPT PLOWED WINTER MONTHS.	
A13	COUNTY ENGINEER LEE ENGSTROM.	
A110-2	DEER ON & INVOF RY.	
A42	Rwy 7/25 marked with Yellow Cones.	
A57	Rwy 25, Trees +14, 242 fm end, 108L, 17:1.	
B31	New Runway length from Geo XH GPS coordinates. 7480 sent with insp report.	
B57	Rwy25: Trees +7, 90 fm end, 18R, 12:1. Need to be lowered 2 feet.	
B57	Rwy 25: Trees +14, 242 fm end, 108L, 17:1. Need to be 2 ft lower.	
A31	Runway length 2531'.	