

CIP JMR -Mora Municipal Airport

State FY	Fed FY	Description	Funding Rates			2012 -2017					Estimated Construction Start Date
			FAA	St	Mun	Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	
2012		LAND ACQ. - YANKOWIAK PARCEL	95	0	5	130,000	123,500	0	6,500	0	1/1/2012
2012		X-WIND RWY 11/29 - CONSTRUCTION	95	0	5	1,200,000	1,140,000	0	60,000	0	1/2/2012
2012		NEW BEACON/RELOCATE WINDSOCK	95	0	5	85,000	80,750	0	4,250	0	1/3/2012
2012		DEER FENCING - PHASE 1	95	0	5	250,000	237,500	0	12,500	0	1/4/2012
2012		TAXILANE REHABILITATION IN BLDG AREA	95	0	5	250,000	237,500	0	12,500	0	1/5/2012
2013		DEER FENCING - PHASE 2	95	0	5	250,000	237,500	0	12,500	0	1/1/2013
2013		AIRPORT LAYOUT PLAN "As-Built"	95	0	5	150,000	142,500	0	7,500	0	1/2/2013
2014		SRE BUILDING	95	0	5	200,000	190,000	0	10,000	0	1/1/2014
2014		TAXILANE REHABILITATION IN BLDG AREA	95	0	5	250,000	237,500	0	12,500	0	1/2/2014
2014		LAND ACQ. - KASTENBAUER PARCEL	95	0	5	35,000	33,250	0	1,750	0	1/3/2014
2015		TAXIWAY LIGHTING	95	0	5	200,000	190,000	0	10,000	0	1/1/2015
2016		10-UNIT T-HANGAR - SITE PREPARATION	95	0	5	75,000	71,250	0	3,750	0	1/1/2016
2016		10-UNIT T-HANGAR - CONSTRUCTION	95	0	5	600,000	570,000	0	30,000	0	1/2/2016

Monday, November 21, 2011

CIP JMR -Mora Municipal Airport

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2017		NO PROJECTS PROGRAMMED	0	0	0	0	0	0	0	0	1/1/2017
			Totals			3,675,000	3,491,250	0	183,750	0	

Summary for Airport = Mora Municipal Airport (14 detail records)

5010 Inspection Remarks:

Last Inspection Year: 2008

Remark Key	Remark	Runway
B57	Rwy 17Obstr by trees 1350 fm end, 250R extend 25 feet into approach surface.	RWY 17
A110-2	WATERFOWL INVOF ARPT.	
A81	ACTVT MIRL RWY 17/35, REIL RYS 17 & 35, & PAPI RYS 17 & 35 - CTAF.	
A40	Fuel Avail 24 Hrs w credit card.	
A110-3	Ultralights on & invof Airport.	
B110-1	Emergency Fuel Shutoff should be marked with sign at pumps.	
B110-2	Rwy 17/35 length change and closing of Rwy 11/29 not documented with FAA.	