

# CIP VVV -Ortonville Municipal Airport - Martinson Field

2012 -2017

State FY	Fed FY	Description	Funding Rates			Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	Estimated Construction Start Date
			FAA	St	Mun						
2013		Construct Taxiway (Finish taxiway to Hangar Sites)	95	0	5	200,000	190,000	0	10,000	0	5/1/2013
2013		RECONSTRUCT ENTRANCE ROAD AND PARKING LOT	95	0	5	180,000	171,000	0	9,000	0	5/15/2013
2015		ARRIVAL/DEPARTURE BUILDING	95	0	5	180,000	171,000	0	9,000	0	5/1/2015
2016		EA for Parallel Taxiway	95	0	5	40,000	38,000	0	2,000	0	10/1/2015
2017		CONSTRUCT PARALLEL TAXIWAY	95	0	5	1,250,000	1,187,500	0	62,500	0	5/1/2017
<b>Totals</b>						<b>1,850,000</b>	<b>1,757,500</b>	<b>0</b>	<b>92,500</b>	<b>0</b>	

Summary for Airport = Ortonville Municipal Airport - Martinson Field (5 detail records)

## 5010 Inspection Remarks:

Last Inspection Year: 2010

Remark Key	Remark	Runway
A30-04	/22 NOT PLOWED WINTER MONTHS.	RWY 04
A42-04	/22 MKD WITH YELLOW CONES.	RWY 04
A110-01	GCO AVBL ON FREQ 121.725 THRU MINNEAPOLIS ARTCC AND PNM AFSS.	
A70	Self serve fuel avail 24 hours: VISA, MC.	
B110-01	Trees & brush in the Prim. Surf. Rwy 16/34, E 16/34 & N 4/22.	
B110-02	Trees in Trans. Surf. Rwy 16/34, E 16/34 & S 4/22.	
B42	Rwy 16/34 paint faded.	
A42	Rwy 16/34 paint faded.	
B110-03	National Based Aircraft count not confirmed.	
A81	Rwy 16/34 lights set to low instst; incr instst - CTAF. Activate PAPI Rwy 16 & Rwy 34 on CTAF.	