

CIP TKC -Tracy Municipal Airport

State FY	Fed FY	Description	Funding Rates			2012 -2017					Estimated Construction Start Date
			FAA	St	Mun	Project Cost	FAA Funding	State Funding	Local Funding	Other Programs	
2012		ROUTE AND SEAL CRACKS	95	0	5	20,000	19,000	0	1,000	0	10/1/2011
2012		INSTALL TIEDOWNS	95	0	5	4,000	3,800	0	200	0	10/2/2011
2012		REPLACE WINDCONE	95	0	5	7,000	6,650	0	350	0	10/3/2011
2015		REHAB RUNWAY	95	0	5	650,000	617,500	0	32,500	0	10/1/2014
2016		TAXILANE PAVING	95	0	5	120,000	114,000	0	6,000	0	10/1/2015
2016		PAVE ENTRANCE ROAD	95	0	5	60,000	57,000	0	3,000	0	10/2/2015
2016		PAVE PARKING LOT	95	0	5	40,000	38,000	0	2,000	0	10/3/2015
2017		HANGAR RENOVATION	0	50	50	40,000	0	20,000	20,000	0	7/1/2016
2017		RUNWAY EXTENSION JUSTIFICATION REPORT	95	0	5	30,000	28,500	0	1,500	0	10/2/2016
2017		ENVIRONMENTAL ASSESSMENT FOR RUNWAY EXTENSION	95	0	5	50,000	47,500	0	2,500	0	10/3/2016
Totals						1,021,000	931,950	20,000	69,050	0	

Summary for Airport = Tracy Municipal Airport (10 detail records)

CIP TKC -Tracy Municipal Airport

2012 -2017

State Fed
FY FY Description

Funding Rates
FAA St Mun

Project
Cost

FAA
Funding

State
Funding

Local
Funding

Other
Programs

Estimated
Construction
Start Date

5010 Inspection Remarks:

Last Inspection Year: 2010

Remark Key	Remark	Runway
A70	CALL ARPT MGR for Service: 507-629-3833 or 507-829-9310.	
A110-2	RYS 06/24 & 17/35 not plowed WINTER MONTHS.	
A42	Rwys 6/24 & RY 17/35 MKD WITH A-FRAMES PAINTED RED & WHITE.	RWY 06
B110-01	Safety and Traffic rules not posted.	
A58	Rwy 29: Tree +15, 60 fm end, 135L.	
B110-02	Trees in Pri surf of Rwy 11/29; remove.	
B57	Rwy 11: TSC Type 3, approaches not approved for night operations.	
B57	Waiver Issued for Rwy 11: 18:1 for road. Data from SEH ALP Submission.	
A81	Incr Intst MIRL Rwy 11-29 - CTAF.	
B42	Rwy 6: missing a corner marker.	
B57	Rwy 17: Road obstructs approach, move end in 30 feet.	
B57	Rwy 35: Trees obstruct approach, lower by 10 feet.	
B57	Rwy 29: Trees obstruct approach.	