

## Two Harbors - TWM

### Two Harbors - Richard B. Helegson Municipal Airport

---

**Associated City:** Two Harbors, MN

**MnDOT Classification:** Intermediate Airport

**NPIAS Airport:** Yes

#### **State Aviation System Plan Airport Data Sheet**

**Commercial Service:** No  
**Cargo Service:** No  
**Flight Training:** Yes  
**On-Demand Charter:** Yes

#### **Primary Runway:**

Designation 6-24  
Length (Feet) 4,400  
Width (Feet) 75  
Average \*PCI Value 63  
Runway Lighting MIRLs

Taxiway Type: Full  
Average \*PCI Value: 66

#### **Crosswind Runway:**

Designation 15-33  
Length (Feet) 2,581  
Width (Feet) 150  
Average \*PCI Value No PCI exists  
Runway Lighting None

Taxiway Type: None  
Average \*PCI Value: -

#### **Other Runways:**

Alternate Runway #1 -  
Alternate Runway #2 -

Notes: \*Pavement Condition Index (PCI) is a value specific to airport pavements as measured by MnDOT. Data provided is for system planning purposes and shall not be used to justify individual improvement projects.

Source: MnDOT Office of Aeronautics 2011 Inventory Survey and Airport Database & HNTB Analysis.