## 2010 CALIBRATION OF DIAL THERMOMETERS (For Bituminous Materials)

## 2010.1 SCOPE

The dial thermometers should be sent to Central Laboratory in Maplewood for calibration before each construction season. They are calibrated in an oil bath through their operating range to a tolerance of  $\pm 2$  °C. Thermometers outside this tolerance will not be returned.

This page intentionally left blank