



MnDOT ADA Compliance Checklist (Curb Ramp)

SP: City: District:

Intersection: Quadrant:

Ramp Type: Const. Year:

Attach a photo of the completed quadrant by clicking here ->

[**DO NOT** use Safari on iPads to upload files]: (6 MB max)

File Attachment

(1) Minimum 4' wide pedestrian access route (PAR) maintained? ☒ Yes ☐ No

(2) Landing meets min. 4'x4' and perpendicular grade break(s)? ☒ Yes ☐ No

(3) Are landing(s) located at the top of each ramp and at change(s) in direction and at inverse grades? ☒ Yes ☐ No

(4) Landing slopes (%): TH TH SS SS

(5) Ramp's running slope (%): TH TH SS SS
Initial Secondary Initial Secondary

(6) Ramp's cross slope (%): TH TH SS SS
Initial Secondary Initial Secondary

(7) Gutter flow line slope (%): TH SS

(8) Gutter inslope (%): TH SS TH = Trunk Highway
SS = Side Street

(9) Roadway cross slope (%): TH SS

(10) Do truncated domes cover the entire curb opening and are they properly oriented? ☒ Yes ☐ No

(11) Are gutter line and ramps draining properly? ☒ Yes ☐ No

(12) Are there any vertical discontinuities greater than 1/4"? ☐ Yes ☒ No

(13) Do ramps comply with Spec 2521.3? ☒ Yes ☐ No

(14) Are ramps fully compliant?

If **NO**, check the reason(s) below. Explain why the ramp didn't meet compliance and how the ramp has been improved from the pre-construction condition (see ADA Compliance Checklist Guidance for more info and attach pages if needed).

☒ Topography ☐ Structure(s) ☐ Utilities ☐ Contractor ☐ MnDOT

File Attachment

(15) Was the curb ramp able to be built according to the plan details? ☐ Yes ☒ No

If NO, explain:

Printed Name: Date (mm/dd/yyyy):

☒ I certify that the information entered on this form is accurate to the best of my knowledge and that I fully understand the checklist standards and am qualified to carry out the inspection.