DEPARTMENT OF TRANSPORTATION

ATP Metro
2019 Pavement Condition

Surface Rating (SR)

- Poor (0.0 - 1.6)
- Fair (1.7 - 2.4)
- Good (2.5 - 4.0)