


Figure 5
Predicted 2020 Pavement Condition
Greenbush-Badger



Document Path: K:\03093-200\GIS\Maps\AssestManagement\Info\Figure 5 - 2020 Pavement.mxd



1 inch = 6,500 feet






Figure 6
Predicted 2020 Pavement Condition
Roseau



Document Path: K:\2020\GIS\MapAssestment\segment6\figure_2020pavement.mxd



2015 mill and overlay on segments 8-10 will raise RQI + approximately 3.5 in 2020

Segment Breaks

RQI

- 3.1 - 5 = Good
- 2.1 - 3 = Fair
- 0 - 2 = Poor

1 inch = 6,500 feet





Figure 7
Predicted 2020 Pavement Condition
Warroad

